

# Release Notes for StarOS™ Software Version 21.10.0 and Ultra Service Platform Version 6.4

First Published: November 2, 2018 Last Updated: November 5, 2018

# Introduction

This Release Note identifies changes and issues related to this software release. This release is the next major feature release since 21.9/N6.3.

# **Release Package Version Information**

| Software Packages   | Version                          |  |
|---|----------------------------------|--|
| StarOS packages   | 21.10, build 70597               |  |
| Ultra Service Platform ISO                                    | 6_4_0-6803                       |  |
| usp-em-bundle*  | 6.4.0, Epoch 4876                |  |
| usp-ugp-bundle*   | 21.10 0, build 70597, Epoch 4815 |  |
| usp-yang-bundle   | 1.0.0, Epoch 4661                |  |
| usp-uas-bundle  | 6.4.0, Epoch 4879                |  |
| usp-auto-it-bundle  | 5.8.0, Epoch 4869                |  |
| usp-vnfm-bundle   | 4.3.0.121, Epoch 4662            |  |
| ultram-manager RPM*   | 2.2.0, Epoch 292                 |  |
| USP RPM Verification Utilities                                | 6.4.0                            |  |
| * These bundles are also distributed separately from the ISO. |                                  |  |

Descriptions for the various packages provided with this release are located in Release Package Descriptions.

**Feature and Behavior Changes** 

# Feature and Behavior Changes

Refer to the Release Change Reference for a complete list of feature and behavior changes associated with this software release.

## **Related Documentation**

For a complete list of documentation available for this release, go to:

- StarOS: https://www.cisco.com/c/en/us/support/wireless/asr-5000-series/products-installation-and-configuration-guides-list.html
- Ultra Gateway Platform (including the Ultra M Solution): <a href="https://www.cisco.com/c/en/us/support/wireless/ultra-gateway-platform/products-installation-and-configuration-guides-list.html">https://www.cisco.com/c/en/us/support/wireless/ultra-gateway-platform/products-installation-and-configuration-guides-list.html</a>
- Ultra Automation Services: <a href="https://www.cisco.com/c/en/us/support/wireless/ultra-automation-services/products-installation-and-configuration-guides-list.html">https://www.cisco.com/c/en/us/support/wireless/ultra-automation-services/products-installation-and-configuration-guides-list.html</a>
- Virtual Packet Core (including VPC-SI and VPC-DI): <a href="https://www.cisco.com/c/en/us/support/wireless/virtual-packet-core/products-installation-and-configuration-guides-list.html">https://www.cisco.com/c/en/us/support/wireless/virtual-packet-core/products-installation-and-configuration-guides-list.html</a>

# Installation and Upgrade Notes

This Release Note does not contain general installation and upgrade instructions. Refer to the existing installation documentation for specific installation and upgrade considerations.

# Ultra M Hyper-Converged Model Component Versions

| HW                             | SW          | 5.8         | 6.0           | 6.1           | 6.2           | 6.3           | 6.4         |
|--------------------------------|-------------|-------------|---------------|---------------|---------------|---------------|-------------|
|                                | StarOS      | 68415       | 21.6.0, Build | 21.7.0, Build | 21.8.0, Build | 21.9.0, Build | 21.10.0,    |
|                                |             |             | 68695         | 68897         | 69296         | 69977         | Build 70597 |
|                                | ESC         | 3.1.0.116   | 3.1.0.145     | 3.1.0.145     | 4.0.0.104     | 4.2.0.74      | 4.3.0.121   |
|                                | RH Kernel   | 7.3         | 7.3           | 7.3           | 7.4           | 7.5           | 7.5         |
|                                | OSP         | 10          | 10            | 10            | 10            | 10            | 10          |
| UCS C240 M4S<br>SFF            | BIOS        | 3.0(3c)     | 3.0(3c)       | 3.0(3c)       | 3.0(4a)       | 3.0(4a)       | 3.0(4a)     |
| (NFVI)                         | CIMC (BMC)  | 3.0(3e)     | 3.0(3e)       | 3.0(3e)       | 3.0(4a)       | 3.0(4d)       | 3.0(4d)     |
|                                | MLOM        | 4.1(3a)     | 4.1(3a)       | 4.1(3a)       | 4.1(3a)       | 4.1(3f)       | 4.1(3f)     |
| C2960XR-48TD-I<br>(Management) | Boot Loader | 15.2(3r)E1  | 15.2(3r)E1    | 15.2(3r)E1    | 15.2(3r)E1    | 15.2(3r)E1    | 15.2(3r)E1  |
| ( 1 01 1 1)                    | IOS         | 15.2.(2) E5 | 15.2.(2) E5   | 15.2.(2) E5   | 15.2.(2) E5   | 15.2.(2) E5   | 15.2.(2) E5 |
| C3850-48T-S<br>(Management)    | Boot Loader | 3.58        | 3.58          | 3.58          | 3.58          | 3.58          | 3.58        |
| , ,                            | IOS         | 03.06.06E   | 03.06.06E     | 03.06.06E     | 03.06.06E     | 03.06.06E     | 03.06.06E   |
| Nexus 93180-<br>YC-EX (Leafs)  | BIOS        | 7.59        | 7.59          | 7.59          | 7.59          | 7.59          | 7.59        |
|                                | NX-OS       | 7.0(3)15(2) | 7.0(3)15(2)   | 7.0(3)17(3)   | 7.0(3)17(3)   | 7.0(3)17(3)   | 7.0(3)17(3) |

Installation and Upgrade Notes

| Nexus 9236C<br>(Spines) | BIOS  | 7.59        | 7.59        | 7.59        | 7.59        | 7.59        | 7.59        |
|-------------------------|-------|-------------|-------------|-------------|-------------|-------------|-------------|
|                         | NX-OS | 7.0(3)15(2) | 7.0(3)15(2) | 7.0(3)17(3) | 7.0(3)17(3) | 7.0(3)17(3) | 7.0(3)17(3) |
|                         |       |             |             |             |             |             |             |


# Firmware Updates

There are no firmware updates required for this release.

# **Software Integrity Verification**

To verify the integrity of the software image you have from Cisco, you can validate the SHA512 checksum information against the checksum identified by Cisco for the software.

Image checksum information is available through **Cisco.com Software Download Details.**To find the checksum, hover the mouse pointer over the software image you have downloaded.



At the bottom you find the SHA512 checksum, if you do not see the whole checksum you can expand it by pressing the "..." at the

To validate the information, calculate a SHA512 checksum using the information in <u>Table 1</u> and verify that it matches either the one provided on the software download page.

Installation and Upgrade Notes

To calculate a SHA512 checksum on your local desktop, see the following table.

Table 1 - Checksum Calculations per Operating System

| Operating System  | SHA512 checksum calculation command examples                                   |
|-------------------|--|
| Microsoft Windows | Open a command line window and type the following command                      |
|                   | > certutil.exe -hashfile <filename>. <extension> SHA512</extension></filename> |
| Apple MAC         | Open a terminal window and type the following command                          |
|                   | \$ shasum -a 512 <filename>. <extension></extension></filename>                |
| Linux             | Open a terminal window and type the following command                          |
|                   | \$ sha512sum <filename>.<extension></extension></filename>                     |
|                   | Or   |
|                   | \$ shasum -a 512 <filename>. <extension></extension></filename>                |
| NOTES:            |  |

#### NOTES:

<filename> is the name of the file.

<extension> is the file extension (e.g. .zip or .tgz).

If the SHA512 checksum matches, you can be sure that no one has tampered with the software image or the image has not been corrupted during download.

If the SHA512 checksum does not match, we advise you to not attempt upgrading any systems with the corrupted software image. Download the software again and verify the SHA512 checksum again. If there is a constant mismatch, please open a case with the Cisco Technical Assistance Center.

## Certificate Validation

StarOS software images are signed via x509 certificates. USP ISO images are signed with a GPG key. Please view the .README file packaged with the software for information and instructions on how to validate the certificates.

**NOTE**: Image signing is not currently supported for VPC-SI and/or VPC-DI software packages.

# Open Bugs in this Release

The following table lists known bugs that were found in, and remain open in this software release.

**NOTE:** This software release may contain open bugs first identified in other releases. Additional information for all open bugs for this release are available in the <u>Cisco Bug Search Tool</u>.

| Bug ID     | Headline  | Product Found* |
|------------|---|----------------|
| CSCvk52151 | [BP-CUPS]: Huge session disconnect with reason sx-cntxt-not-found                                   | cups-cp        |
| CSCvm48160 | [PLT-CUPS] chmgr restart unhandled sn_event_file's in migrating proclet chmgr                       | cups-cp        |
| CSCvi53376 | [BP-CUPS]: Session Manager reload at smgr_uplane_config_rule_options on Cisco PGW                   | cups-up        |
| CSCvk52159 | [BP-CUPS]: huge session disconnect with reason sx-mand-ie-incorrect                                 | cups-up        |
| CSCvk56280 | [BP-CUPS-VPP]: sessmgr restart at uplane_policing_charging  | cups-up        |
| CSCvk62265 | [BP-CUPS]: UP never re-initiate SX association if it comes back before SX faillure detected in UP   | cups-up        |
| CSCvk66464 | [BP-CUPS]: Sessmgr reload at smgr_match_dyn_rule_filter   | cups-up        |
| CSCvm54234 | [PLT-CUPS-VPP] Call is getting dropped after performing shutdown-noshutdown-shutdown interface      | cups-up        |
| CSCvk46857 | [PLT-CUPS-VPP]: vpnmgr restart while removing crp config  | cups-up        |
| CSCvm47437 | [BP-ICUPS]: Analyser/RB statistics are not counting DL dropped offloaded packets.                   | cups-up        |
| CSCvm56058 | [BP-ICUPS]: Streams created with state PASSIVE and packets pass through slow path.                  | cups-up        |
| CSCvm56190 | [BP-ICUPS]: packets sent through slow path after PDN-UPDATE.  | cups-up        |
| CSCvm57966 | [BP-ICUPS] First DL pkt of UDP flow creating stream in passive state instead of active state        | cups-up        |
| CSCvm72250 | [PLT-CUPS-ICUPS] sessmgr and vpp crashes and DPC2 cards in Offline state on 21.10.M0.70328          | cups-up        |
| CSCvm50353 | [BP-ICUPS] : SGW sends TEP entry Updation with IPV6 remote and local address during HO              | pdn-gw         |
| CSCvm55782 | [BP-ICUPS]:Dynamic Rule flow status change from Discard to Allow All is not working                 | pdn-gw         |
| CSCvm63590 | [PLT-ICUPS-VPP]: Update to DCCA triggered 1 pkt later then expected.                                | pdn-gw         |
| CSCvm79365 | [BP-ICUPS]: Data over new dedicated bearer after gngp-collapsed HO sent through slow path.          | pdn-gw         |
| CSCvm91229 | [BP-ICUPS] : sessmgr restart at fapi_tp_process_incoming_local_row_req() sp=0xffccd588()            | pdn-gw         |
| CSCvm75776 | [BP-ICUPS]:Policer table is deleted,created twice on Dynamic Rule deletion, bearer movement for GBR | pdn-gw         |
| CSCvm83968 | [CUSP] need to handle interworking of URL-readdressing and CUSP feature.                            | pdn-gw         |
| CSCvn03518 | Idle timer expires 10 seconds earlier than it ideally should when data sent.                        | pdn-gw         |
| CSCvn13800 | sessmgr restart at function dh_api_delete_handle  | pdn-gw         |
| CSCvm82008 | [BP-ICUPS]:HTTP volume based offload is not happening after PDN update                              | sae-gw         |

Resolved Bugs in this Release

| .0_70287_SGSN: Subscriber IMEI check frequency config not working properly during rSRAU event | sgsn    |
|---|---------|
|   | 1       |
| SN] DNS Naptr weight based load balancing not taking place                                    | sgsn    |
| -ICUPS]:TCP & UDP Packets drop observed at VPP for Single PGW at 500+ Mbps with 5 & ws        | staros  |
| ctivation failure due to timeout at AutoVNF   | usp-uas |
| OVNF NETCONF trace has passwords in the clear   | usp-uas |
| Diags not working correctly   | usp-usf |
| Diag  | ·       |

# Resolved Bugs in this Release

The following table lists known bugs that are resolved in this specific software release.

**NOTE:** This software release may contain bug fixes first introduced in other releases. Additional information for all resolved bugs for this release are available in the <u>Cisco Bug Search Tool</u>.

| Bug ID     | Headline  | Product Found* |
|------------|---|----------------|
| CSCvj77515 | [BP-CUPS]: sessmgr restart when attempting an SAEGW Gx call on CUPS setup                           | cups-cp        |
| CSCvk13379 | [BP-CUPS]Sessmgr reload is observed on PGW Control Plane while sending Sx Session Reporting Request | cups-cp        |
| CSCvk48006 | [BP-CUPS]: Behaviour on Sx PFD messages timeout - UP stuck in Not configured state                  | cups-cp        |
| CSCvk56822 | [BP-CUPS]:Sx Path failure causing call drop after srp switch-over                                   | cups-cp        |
| CSCvk54440 | StarOS 21.9 release does not contain the unittest for the traps with ifIndexes from 1357 to 1360    | cups-cp        |
| CSCvk21427 | [BP-CUPS-VPP] Seg Fault at sessmgr_up_fapi_handle_stats_update()                                    | cups-up        |
| CSCvk47500 | [BP-CUPS-VPP] RS packet handling is incorrect in VPP fastpath.                                      | cups-up        |
| CSCvk58383 | [BP-CUPS-VPP] Assertion failure at Function: sxmgr_process_session_establish_req                    | cups-up        |
| CSCvk62132 | [PLT-CUPS-VPP] IP fragmented packets are dropped by VPP   | cups-up        |
| CSCvk65470 | [BP-CUPS] sessmgr resrart libc.so.6/strlen_sse2_bsf()   | cups-up        |
| CSCvm06471 | [BP-CUPS-VPP] Sessmgr reload at uplane_reset_saved_pdr_match_info                                   | cups-up        |
| CSCvm08142 | [BP-CUPS]:Sessmgr reload at uplane_http_accel_check.isra.116  | cups-up        |
| CSCvm08681 | [BP-CUPS]: sessmgr reload at set_stream_operations  | cups-up        |
| CSCvj76251 | [PLT-CUPS-VPP]: vpp_main in 'over' state with single subscriber 8Mbps data                          | cups-up        |
| CSCvj81306 | [BP-CUPS]: [sessmgr 12341 error] [SXAB] Update PDR not found with PDR ID 0x7                        | cups-up        |
| CSCvk39031 | [BP-CUPS-VPP] TOS not getting applied on d/l inner packet from qci qos mapping table.               | cups-up        |

## Resolved Bugs in this Release

| Bug ID     | Headline  | Product Found* |
|------------|---|----------------|
| CSCvk40097 | [BP-CUPS]: Sessmgr restarted with sn_slist_remove_by_key  | cups-up        |
| CSCvk42806 | [BP-CUPS-VPP] Drop stream is not getting onloaded on installing high priority rule.                 | cups-up        |
| CSCvk51032 | [BP-CUPS-VPP] sessmgr crash(seg fault)sx_tun_fsm_handle_sess_mod_rsp_evt                            | cups-up        |
| CSCvk54274 | [BP-CUPS]: UP is crashing and call in not coming up when subs-class with rulebase config is present | cups-up        |
| CSCvk55699 | [BP-CUPS]: Issues with un-optimized rules in GoR. Traffic always matches Un-optimised rules in GOR  | cups-up        |
| CSCvk56186 | [PLT-CUPS-VPP] LC row is not removed on removal of URR.   | cups-up        |
| CSCvk56305 | Sessmgr restart seen when the link btw CP and UP are broken for some reason                         | cups-up        |
| CSCvk56703 | [PLT-CUPS-VPP]: 200k scaling test vpp restart memif_interface_tx ()                                 | cups-up        |
| CSCvk58697 | [BP-CUPS-VPP] US37480: Support correct charging of packets which do not go for RuleMatch            | cups-up        |
| CSCvk64528 | [BP-CUPS-VPP]: user-plane rule base statistics packet count swapped                                 | cups-up        |
| CSCvm00476 | [BP-CUPS] sxdemux facility in over state  | cups-up        |
| CSCvm09336 | [BP-CUPS] "show subscribers user-plane-only" discrepancy with active flow output                    | cups-up        |
| CSCvm20512 | [BP-CUPS-VPP] sessmgr restart on rulebase change from egcdr disable to enable.                      | cups-up        |
| CSCvm36773 | [PLT-ICUPS-VPP] Stream Operations not working after stream-modify                                   | cups-up        |
| CSCvm46282 | [BP-ICUPS-VPP]L3 L4 actions not applied on UL streams for pipelined GET                             | cups-up        |
| CSCvm47423 | [BP-ICUPS] : CA level TOS marking is not getting applied for HTTP onloaded response packets         | cups-up        |
| CSCvm55905 | [BP-ICUPS]: packets sent through slow path after HO.  | cups-up        |
| CSCvm66988 | [BP-ICUPS]:HTTP volume based offload not working correctly  | cups-up        |
| CSCvm47411 | [BP-ICUPS] Total Accel Pkts counter is not incremented in under FTP Analyzer statistics             | cups-up        |
| CSCvm51442 | [GGSN/PGW] Right PDP failure cause for supported IPv6 should be "Unknown PDP address or PDP type"   | ggsn           |
| CSCvk68643 | Ruledef with imsi pool configuration not getting matched appropriately                              | ipsg           |
| CSCvm77890 | [BP-ICUPS]: UDP UL/DL pkts are dropping for dedicated bearer(GBR bearer).                           | pdn-gw         |
| CSCvj09057 | PGW detect wrong RAI change event trigger when ULI change from CGI+RAI to CGI                       | pdn-gw         |
| CSCvk27330 | PGW retransmits Gy CCR-U without previous USU AVP in case of RAR-CCR collision                      | pdn-gw         |
| CSCvk29371 | <br><b>gtpc peer-salvation</b> keyword is missing under context level configuration                 | pdn-gw         |
| CSCvk43057 | Sessmgr restart seen at PGW while adding frame route received from radius.                          | pdn-gw         |
| CSCvk59689 | PGW: CCR sent with wrong Destination Realm after Gx recovery  | pdn-gw         |
| CSCvk61018 | [BP-ICUPS]:offloaded packets are counted double in active charging flows all output                 | pdn-gw         |
|            | <u> </u>  | L              |

## Resolved Bugs in this Release

| Bug ID     | Headline  | Product Found* |
|------------|---|----------------|
| CSCvk65827 | [BP-ICUPS] : Uplink data not reaching PDN side  | pdn-gw         |
| CSCvm03497 | Multiple sessmgrs to go into warn state due to high memory at Cisco PGW                           | pdn-gw         |
| CSCvm05227 | [BP-ICUPS-] sessmgr restart on single pgw call when tried to increase throughput beyond 4Gb.      | pdn-gw         |
| CSCvm06442 | [BP-ICUPS]: Garbage TIME-IDLE value in show sub all for downlink udp traffic                      | pdn-gw         |
| CSCvm08447 | [BP-ICUPS]:L4 TCP/UDP Bytes are not getting correctly updated in analyser stats                   | pdn-gw         |
| CSCvm16264 | [BP-ICUPS] fastpath_stream_add():sessmgr error logs (streams not created/no LCs updated)          | pdn-gw         |
| CSCvm33939 | [BP-ICUPS-VPP]:Sessmgr restart at migrate_clnt_prepare_procl_for_migration() function             | pdn-gw         |
| CSCvm34028 | [BP-ICUPS] : After Recovery, data packets through sessmgr   | pdn-gw         |
| CSCvm47811 | Adding debug info to understand restart counter change from SGW causing PGW to mark sessions down | pdn-gw         |
| CSCvm50715 | [BP-ICUPS]:acsmgr_process_fp_flow_stats() casuses sessmgr restart                                 | pdn-gw         |
| CSCvm50721 | [BP-ICUPS]:After AMBR change acs_handle_sess_event_notify() seen                                  | pdn-gw         |
| CSCvm55788 | [BP-ICUPS]:sessmgr restart observed on collocated calls and with http traffic on TMO setup.       | pdn-gw         |
| CSCvm74718 | [BP-ICUPS] : PC: [097a0248/X] is_acs_rule_dscp_enabled()  | pdn-gw         |
| CSCvm81755 | [BP-ICUPS]: Bandwidth Policy Flow Id change after Rulebase change is not getting applied          | pdn-gw         |
| CSCvm83704 | egtpinmgr restart when MIO switchover happened  | pdn-gw         |
| CSCvm83730 | [BP-ICUPS] [ICSR] Crash in sessmgr_fp_recover_clp_abstract_data during ICSR                       | pdn-gw         |
| CSCvm89565 | [BP-ICUPS]: UDP downlink data is dropped on 70457   | pdn-gw         |
| CSCvn00082 | Create Session Response with MSISDN PCO Option fails with consecutive 0's                         | pdn-gw         |
| CSCvj35699 | Session manager task restart observed while applying url-readdressing.                            | pdn-gw         |
| CSCvk14784 | Accelerated flows are not ITC BW-limited when BW-ID configured in charging-action.                | pdn-gw         |
| CSCvm36611 | Cisco PGW Egtpmgr restart seen after CLI "show egtpc peers path-failure-history"                  | pdn-gw         |
| CSCvm54632 | Session manager on standby chassis is in memory over state.                                       | pdn-gw         |
| CSCvm83724 | [BP-ICUPS]:Data is not offloaded after PDN update is done via dyn rule installation               | sae-gw         |
| CSCvm54230 | Cause Source bit discrepancy within Create Bearer Response message on SPGW                        | sae-gw         |
| CSCvm62241 | ASR5500- Assertion failure at sess/smgr/sessmgr_pgw_li.c:450                                      | sae-gw         |
| CSCvj83211 | SM fail due to Fatal Signal at <unknown></unknown>  | sgsn           |
| CSCvd89962 | sessmgr Assertion Failure in egtpc_handle_user_sap_event()  | sgsn           |

#### **Operator Notes**

| Bug ID  | Headline  | Product Found* |
|---|---|----------------|
| CSCvk47572  | Duplicate messages over S13 interface.  | sgsn           |
| CSCvj49375  | Session manager restart due to EGTPC Update bearer response event                 | sgsn           |
| CSCvj81432  | Periodic card shutdown observed on Standby CF card.                               | staros         |
| CSCvf65641  | Consecutive EGTPCPathFailClear SNMP traps without EGTPCPathFailSet                | staros         |
| CSCvm73155  | Unable to update module p2p after unplanned DPC migration                         | staros         |
| CSCvi12895  | FloatingIP assignment should be unique across VMs of VNFs                         | usp-uas        |
| CSCvj85201  | ultram-health uas report Authentication failed                                    | usp-uas        |
| CSCvj04691  | AutoVNF recovery post upgrade does not spawn the upgraded image                   | usp-uas        |
| CSCvj04799  | AutoVNF upgrade failure - rollback to secondary image does not happen             | usp-uas        |
| CSCvk60364  | Deactivation failure due to timeout at AutoVNF                                    | usp-uas        |
| CSCvk56974  | CUPS: Simultaneous undeployment for multiple vnfds leaves vnfd in Stopping state. | usp-usf        |
| CSCvm03898  | VnfDiags not working correctly  | usp-usf        |
| * Information in the "Product Found" column identifies the product in which the bug was initially identified. |   |                |

# **Operator Notes**

## StarOS Version Numbering System


The output of the **show version** command displays detailed information about the version of StarOS currently running on the ASR 5x00 or Cisco Virtualized Packet Core platform.

Prior to release 16.1, the *Image Version* field displayed a branch of software including the build number, for example "16.0 (55435)". Subsequent releases of software for the major release differed only in build number. Lab Quality/EFT releases versus deployment releases also differed only in build number.


From release 16.1 onwards, the output of the **show version** command, as well as the terminology used to describe the Build Version Number fields, has changed. Additionally, **show version** will display slightly different information depending on whether or not a build is suitable for deployment.

The Version Build Number for releases between 16.1 and 21.0 include a major, maintenance, and emergency release number, for example "16.1.2".

Operator Notes



The Version Build Number for releases 21.1 and later include a major and emergency release number, for example, "21.1.1".



In either scenario, the appropriate version number field increments after a version has been released. The new version numbering format is a contiguous sequential number that represents incremental changes between releases. This format will facilitate identifying the changes between releases when using Bug Search Tool to research software releases.

# **Release Package Descriptions**

Table 2 lists provides descriptions for the packages that are available with this release.

Table 2 - Release Package Information

| Package                            | Description  |
|------------------------------------|--|
| ASR 5500                           |  |
| asr5500- <release>.bin</release>   | A zip file containing the signed ASR 5500 software image, the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate.          |
| asr5500_T- <release>.bin</release> | A zip file containing the signed, trusted ASR 5500 software image, the signature file, a verification script, the x509 certificate, and a README file containing information on how to use the script to validate the certificate. |
| VPC-DI                             |  |

## Operator Notes

| Package   | Description  |
|---|--|
|   | '  |
| qvpc-di- <release>.bin</release>                            | The VPC-DI binary software image which is used to replace a previously deployed image on the flash disk in existing installations.         |
| qvpc-di_T- <release>.bin</release>                          | The trusted VPC-DI binary software image which is used to replace a previously deployed image on the flash disk in existing installations. |
| qvpc-di- <release>.iso</release>                            | The VPC-DI ISO used for new deployments a new virtual machine is manually created and configured to boot from a CD image.                  |
| qvpc-di_T- <release>.iso</release>                          | The trusted VPC-DI ISO used for new deployments a new virtual machine is manually created and configured to boot from a CD image.          |
| qvpc-di-template-<br>vmware- <release>.tgz</release>        | The VPC-DI binary software image that is used to on-board the software directly into Vmware.   |
| qvpc-di-template-<br>vmware_T- <release>.tgz</release>      | The trusted VPC-DI binary software image that is used to on-board the software directly into Vmware.                                       |
| qvpc-di-template-libvirt-<br>kvm- <release>.tgz</release>   | This is an archive that includes the same VPC-DI ISO identified above, but additional installation files for using it on KVM.              |
| qvpc-di-template-libvirt-<br>kvm_T- <release>.tgz</release> | This is an archive that includes the same trusted VPC-DI ISO identified above, but additional installation files for using it on KVM.      |
| qvpc-di-<br><release>.qcow2.tgz</release>                   | The VPC-DI binary software image in a format that can be loaded directly with KVM using an XML definition file, or with OpenStack.         |
| qvpc-di_T-<br><release>.qcow2.tgz</release>                 | The trusted VPC-DI binary software image in a format that can be loaded directly with KVM using an XML definition file, or with OpenStack. |
| VPC-SI  |  |
| qvpc-si- <release>.bin</release>                            | The VPC-SI binary software image which is used to replace a previously deployed image on the flash disk in existing installations.         |
| qvpc-si_T- <release>.bin</release>                          | The trusted VPC-SI binary software image which is used to replace a previously deployed image on the flash disk in existing installations. |
| qvpc-si- <release>.iso</release>                            | The VPC-SI ISO used for new deployments a new virtual machine is manually created and configured to boot from a CD image.                  |
| qvpc-si_T- <release>.iso</release>                          | The trusted VPC-SI ISO used for new deployments a new virtual machine is manually created and configured to boot from a CD image.          |
| qvpc-si-template-vmware-<br><release>.ova</release>         | The VPC-SI binary software image that is used to on-board the software directly into Vmware.   |
| qvpc-si-template-<br>vmware_T- <release>.ova</release>      | The trusted VPC-SI binary software image that is used to on-board the software directly into Vmware.                                       |
| qvpc-si-template-libvirt-<br>kvm- <release>.tgz</release>   | This is an archive that includes the same VPC-SI ISO identified above, but additional installation files for using it on KVM.              |
| qvpc-si-template-libvirt-<br>kvm_T- <release>.tgz</release> | This is an archive that includes the same trusted VPC-SI ISO identified above, but additional installation files for using it on KVM.      |
| qvpc-si- <release>.<br/>qcow2.gz</release>                  | The VPC-SI binary software image in a format that can be loaded directly with KVM using an XML definition file, or with OpenStack.         |

Obtaining Documentation and Submitting a Service Request

| Package  | Description  |  |
|--|--|--|
| qvpc-si_T- <release>.</release>                  | The trusted VPC-SI binary software image in a format that can be loaded directly with KVM using an   |  |
| qcow2.gz   | XML definition file, or with OpenStack.  |  |
|  |  |  |
| StarOS Companion Package                         |  |  |
| companion- <release>.tgz</release>               | An archive containing numerous files pertaining to this version of the StarOS including SNMP MIBs, RADIUS dictionaries, ORBEM clients. These files pertain to both trusted and non-trusted build variants. |  |
| Ultra Service Platform                           |  |  |
| usp- <version>.iso</version>                     | The USP software package containing component RPMs (bundles).  |  |
|  | Refer to <u>Table 3</u> for descriptions of the specific bundles.  |  |
| usp_T- <version>.iso</version>                   | The USP software package containing component RPMs (bundles). This bundle contains trusted images.   |  |
|  | Refer to Table 3 for descriptions of the specific bundles.   |  |
| usp_rpm_verify_utils-<br><version>.tar</version> | This package contains information and utilities for verifying USP RPM integrity.   |  |

## Table 3 - USP ISO Bundles

| USP Bundle Name   | Description   |  |
|---|---|--|
| usp-em-bundle- <version>-<br/>1.x86_64.rpm*</version>         | The Element Manager (EM) Bundle RPM containing images and metadata for the Ultra Element Manager (UEM) module.  |  |
| usp-ugp-bundle-<br><version>-1.x86_64.rpm*</version>          | The Ultra Gateway Platform (UGP) Bundle RPM containing images for Ultra Packet core (VPC-DI).  There are trusted and non-trusted image variants of this bundle. |  |
| usp-yang-bundle-<br><version>-1.x86_64.rpm</version>          | The Yang Bundle RPM containing YANG data models including the VNFD and VNFR.  |  |
| usp-uas-bundle- <version>-<br/>1.x86_64.rpm</version>         | The Ultra Automation Services Bundle RPM containing AutoVNF, Ultra Web Services (UWS), and other automation packages.   |  |
| usp-auto-it-bundle-<br><version>-1.x86_64.rpm</version>       | The bundle containing the AutoIT packages required to deploy the UAS.   |  |
| usp-vnfm-bundle-<br><version>-1.x86_64.rpm</version>          | The VNFM Bundle RPM containing an image and a boot-up script for ESC (Elastic Service Controller).  |  |
| ultram-manager-<br><version>-1.x86_64.rpm</version>           | This package contains the script and relevant files needed to deploy the Ultra M Manager Service.   |  |
| * These bundles are also distributed separately from the ISO. |   |  |

# Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see *What's New in Cisco Product Documentation*, at:

http://www.cisco.com/c/en/us/td/docs/general/whatsnew/whatsnew.html.

Obtaining Documentation and Submitting a Service Request

Subscribe to What's New in Cisco Product Documentation, which lists all new and revised Cisco technical documentation, as an RSS feed and deliver content directly to your desktop using a reader application. The RSS feeds are a free service.

Obtaining Documentation and Submitting a Service Request

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies are considered un-Controlled copies and the original on-line version should be referred to for latest version.

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco website at <a href="https://www.cisco.com/go/offices">www.cisco.com/go/offices</a>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <a href="www.cisco.com/go/trademarks">www.cisco.com/go/trademarks</a>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2018 Cisco Systems, Inc. All rights reserved.