

Nexus 9000 TCAM values set to 0 dropping Arp, UDLD, LACP packets

Contents

[Introduction](#)

[Prerequisite](#)

[Topology](#)

[Troubleshooting](#)

[Analysis](#)

[Solution](#)

[Useful commands](#)

[Useful links](#)

Introduction

This document explains how to troubleshoot when Nexus 9000 TCAM when ports go down due to UDLD error

It cover the current and common concepts, troubleshooting methods and error messages.

The purpose of this document is to help users understand how to troubleshoot TCAM when ports go down due to UDLD error


Prerequisite

Understanding of Cisco NXOS commands

[NXOS TCAM configuration](#)

Topology

The issue can be seen with a simple topology



Troubleshooting

Following protocols fail to work on control plane:

ARP resolution fail

Ports on Nexus 9000 reported down due to UDLD error for module 1 & 2.

```
N9K-1(config-if)# 2018 Oct 20 07:23:23 N9K-1 %ETHPORT-5-IF_ADMIN_UP: Interface port-channel100
is admin up .
2018 Oct 20 07:23:23 N9K-1 %ETHPORT-5-IF_DOWN_PORT_CHANNEL_MEMBERS_DOWN: Interface port-
channel100 is down (No operational members)
2018 Oct 20 07:23:23 N9K-1 last message repeated 1 time
2018 Oct 20 07:23:23 N9K-1 %ETHPORT-5-IF_DOWN_ERROR_DISABLED: Interface Ethernet2/2 is down
(Error disabled. Reason:UDLD empty echo)
2018 Oct 20 07:23:23 N9K-1 last message repeated 1 time
2018 Oct 20 07:23:23 N9K-1 %ETHPORT-5-IF_DOWN_ERROR_DISABLED: Interface Ethernet2/1 is down
(Error disabled. Reason:UDLD empty echo)
sh 2018 Oct 20 07:23:25 N9K-1 last message repeated 1 time
```

Line cards fail due to **L2ACLRedirect** diagnostic test on chassis for module 1 & 2.

'Show module'

```
Mod  Online Diag Status
---  -----
1    Fail-----cleared the module 1 and 2 error .[show logging nvram]
2    Fail-----module 2 reloaded.
3    Pass
```

Module 1 and 2:

```
11) L2ACLRedirect-----> E
12) BootupPortLoopback: U
```

Another Possible way customer can hit this state is SUP/LC from a T2 ASIC based chassis moved to Tahoe based chassis

Note: If you want to know more information about ASIC troubleshooting please contact cisco TAC

[CSCvc36411](#) Upgrading from T2 to Tahoe based line cards / FM can cause diagnostic failure and TCAM issues

Analysis

This issue would be seen when TCAM Values set to 0 on N9K-2

'Show module'

```
Mod  Online Diag Status
---  -----
1    Fail-----cleared the module 1 and 2 error .[show logging nvram]
2    Fail-----module 2 reloaded.
3    Pass
```

Module 1 and 2:

```
11) L2ACLRedirect-----> E
12) BootupPortLoopback: U
```

To isolate further remove UDLD and but ping fail to work

Arp request going out of N9K-2

```
N9K-2# ethanalyzer local interface inband
```

```
Capturing on inband
```

```
2018-10-23 10:46:47.282551      1.1.1.1 -> 1.1.1.2      ICMP Echo (ping) request
2018-10-23 10:46:47.286072 b0:aa:77:30:75:bf -> ff:ff:ff:ff:ff:ff ARP Who has 1.1.1.1? Tell
1.1.1.2
2018-10-23 10:46:49.284704      1.1.1.1 -> 1.1.1.2      ICMP Echo (ping) request
2018-10-23 10:46:51.286150 b0:aa:77:30:75:bf -> ff:ff:ff:ff:ff:ff ARP Who has 1.1.1.1? Tell
1.1.1.2
2018-10-23 10:46:51.286802      1.1.1.1 -> 1.1.1.2      ICMP Echo (ping) request
2018-10-23 10:46:53.288989      1.1.1.1 -> 1.1.1.2      ICMP Echo (ping) request
2018-10-23 10:46:55.289920      1.1.1.1 -> 1.1.1.2      ICMP Echo (ping) request
2018-10-23 10:46:57.292070      1.1.1.1 -> 1.1.1.2      ICMP Echo (ping) request
2018-10-23 10:46:59.292568      1.1.1.1 -> 1.1.1.2      ICMP Echo (ping) request
2018-10-23 10:46:59.292818 b0:aa:77:30:75:bf -> ff:ff:ff:ff:ff:ff ARP Who has 1.1.1.1? Tell
1.1.1.2
10 packets captured
```

```
N9K-1# ethanalyzer local interface inband
```

```
Capturing on inband
```

```
2018-10-23 04:02:40.568119 b0:aa:77:30:75:bf -> ff:ff:ff:ff:ff:ff ARP Who has 1.1.1.1? Tell
1.1.1.2
2018-10-23 04:02:40.568558 cc:46:d6:af:ff:bf -> b0:aa:77:30:75:bf ARP 1.1.1.1 is at
cc:46:d6:af:ff:bf
2018-10-23 04:02:48.574800 b0:aa:77:30:75:bf -> ff:ff:ff:ff:ff:ff ARP Who has 1.1.1.1? Tell
1.1.1.2
2018-10-23 04:02:48.575230 cc:46:d6:af:ff:bf -> b0:aa:77:30:75:bf ARP 1.1.1.1 is at
cc:46:d6:af:ff:bf—arp reply packet sent by aggl.
```

ELAM on N9K-2 has ARP response from N9K-1

Note: Please contact Cisco TAC to verify ELAM capture

```
module-2(TAH-elam-insel6)# reprot
```

```
Initting block addresses
```

```
SUGARBOWL ELAM REPORT SUMMARY
```

```
slot - 2, asic - 1, slice - 0
=====
```

```
Incoming Interface: Eth2/2
Src Idx : 0x42, Src BD : 4489
Outgoing Interface Info: dmod 0, dpid 0
Dst Idx : 0x0, Dst BD : 4489
```

Packet Type: ARP

```
Dst MAC address: B0:AA:77:30:75:BF
Src MAC address: CC:46:D6:AF:FF:BF
Target Hardware address: B0:AA:77:30:75:BF ----- Arp packet
captured on Linecard
Sender Hardware address: CC:46:D6:AF:FF:BF
Target Protocol address: 1.1.1.2
```

Sender Protocol address: 1.1.1.1

ARP opcode: 2

Drop Info:

module-2(TAH-elam-insel6)#

Bug ping still fail

module-2(TAH-elam-insel6)# reprot

Initting block addresses

SUGARBOWL ELAM REPORT SUMMARY

slot - 2, asic - 1, slice - 0

=====

Incoming Interface: Eth2/2

Src Idx : 0x42, Src BD : 4489

Outgoing Interface Info: dmod 0, dpid 0

Dst Idx : 0x0, Dst BD : 4489

Packet Type: ARP

Dst MAC address: B0:AA:77:30:75:BF

Src MAC address: CC:46:D6:AF:FF:BF

Target Hardware address: B0:AA:77:30:75:BF ----- Arp packet captured on Linecard

Sender Hardware address: CC:46:D6:AF:FF:BF

Target Protocol address: 1.1.1.2

Sender Protocol address: 1.1.1.1

ARP opcode: 2

Drop Info:

module-2(TAH-elam-insel6)#

module-2(TAH-elam-insel6)# reprot

Initting block addresses

SUGARBOWL ELAM REPORT SUMMARY

slot - 2, asic - 1, slice - 0

=====

Incoming Interface: Eth2/2

Src Idx : 0x42, Src BD : 4489

Outgoing Interface Info: dmod 0, dpid 0

Dst Idx : 0x0, Dst BD : 4489

Packet Type: ARP

Dst MAC address: B0:AA:77:30:75:BF

Src MAC address: CC:46:D6:AF:FF:BF

Target Hardware address: B0:AA:77:30:75:BF ----- Arp packet captured on Linecard

Sender Hardware address: CC:46:D6:AF:FF:BF

Target Protocol address: 1.1.1.2

Sender Protocol address: 1.1.1.1

ARP opcode: 2

Drop Info:

module-2(TAH-elam-insel6)#

To isolate arp issue add a static arp entry and disable UDLD

After static arp ping from 1.1.1.2 to 1.1.1.1 started working but it would fail again if UDLD is enabled

```
module-2(TAH-elam-insel6)# reprot
```

```
Initting block addresses
```

```
SUGARBOWL ELAM REPORT SUMMARY
```

```
slot - 2, asic - 1, slice - 0
```

```
=====
```

```
Incoming Interface: Eth2/2
```

```
Src Idx : 0x42, Src BD : 4489
```

```
Outgoing Interface Info: dmod 0, dpid 0
```

```
Dst Idx : 0x0, Dst BD : 4489
```

Packet Type: ARP

Dst MAC address: B0:AA:77:30:75:BF

Src MAC address: CC:46:D6:AF:FF:BF

Target Hardware address: B0:AA:77:30:75:BF ----- Arp packet captured on Linecard

Sender Hardware address: CC:46:D6:AF:FF:BF

Target Protocol address: 1.1.1.2

Sender Protocol address: 1.1.1.1

ARP opcode: 2

Drop Info:

```
module-2(TAH-elam-insel6)#
```

Though ping works the UDLD errors would still be seen on the interface when enabled

No CoPP drops as seen below

```
module-2(TAH-elam-insel6)# reprot
```

```
Initting block addresses
```

```
SUGARBOWL ELAM REPORT SUMMARY
```

```
slot - 2, asic - 1, slice - 0
```

```
=====
```

```
Incoming Interface: Eth2/2
```

```
Src Idx : 0x42, Src BD : 4489
```

```
Outgoing Interface Info: dmod 0, dpid 0
```

```
Dst Idx : 0x0, Dst BD : 4489
```

Packet Type: ARP

Dst MAC address: B0:AA:77:30:75:BF

Src MAC address: CC:46:D6:AF:FF:BF

Target Hardware address: B0:AA:77:30:75:BF ----- Arp packet captured on Linecard

Sender Hardware address: CC:46:D6:AF:FF:BF

Target Protocol address: 1.1.1.2

Sender Protocol address: 1.1.1.1


```

----- 6      Local AXP CPU   Yes   UP   No   2   6
781502852 1006219901  6868852  3506128 7 This SC BCM EOBC switch  Yes   UP   No
 2   6  654791960 430206276  1833465  3523170 8 Other SC BCM EOBC switch  Yes
DOWN No   2   6   72282   176   3   2 9 This SC EPC switch  Yes   UP
No   2   6  351355874 351309506  1672662  3345683 Switch type: Marvell 98DXN11 - 10
port switchPort Descr          Enable Status ANeg Speed Mode InByte OutByte InPkts
OutPkts----- 0      FM6
EPC switch  Yes  DOWN No   2   6   0   0   0   0 1  FM5 EPC switch
  Yes  DOWN No   2   6   0   0   0   0 2  SUP ALT EPC  Yes
DOWN No   2   6   0   0   0   0 3  SUP PRI EPC  Yes  DOWN No
 2   6   0   0   0   0 4  FM4 EPC switch  Yes  DOWN No   2   6
 0   0   0   0 5  FM3 EPC switch  Yes  DOWN No   2   6   0   0
 0   0 6  FM2 EPC switch  Yes  DOWN No   2   6   0   0   0
0 7  FM1 EPC switch  Yes  DOWN No   2   6   0   0   0   0 8 Other
SC EPC switch  Yes   UP No   2   6 351356399 351310095  1672664  3345687 9
Local SC 4-port switch  Yes   UP No   2   6 351310031 351356399  3345688
1672664Rule Rule_name          Match_ctr          Pol_en Pol_idx inProfileBytes
outOfProfileBytes-----

```

Solution

TCAM Values set to 0 cause dropping of all control traffic in the linecard .

After changing the TCAM values to the default uddl comes up and arp gets resolved

Configuration added to N9K-2 to solve the issue

Reload is needed after the configuration change

```

module-30# show mvdxn internal port-status

```

```

Switch type: Marvell 98DXN41 - 4 port switch
Port Descr          Enable Status ANeg Speed Mode InByte OutByte InPkts
OutPkts
-----
6      Local AXP CPU   Yes   UP   No   2   6  781502852 1006219901  6868852
3506128
7 This SC BCM EOBC switch  Yes   UP   No   2   6  654791960 430206276  1833465
3523170
8 Other SC BCM EOBC switch  Yes  DOWN No   2   6   72282   176   3
2
9 This SC EPC switch  Yes   UP   No   2   6  351355874 351309506  1672662
3345683

Switch type: Marvell 98DXN11 - 10 port switch
Port Descr          Enable Status ANeg Speed Mode InByte OutByte InPkts
OutPkts
-----
0      FM6 EPC switch  Yes  DOWN No   2   6   0   0   0
0
1      FM5 EPC switch  Yes  DOWN No   2   6   0   0   0
0

```

2	0	SUP ALT EPC	Yes	DOWN	No	2	6	0	0	0
3	0	SUP PRI EPC	Yes	DOWN	No	2	6	0	0	0
4	0	FM4 EPC switch	Yes	DOWN	No	2	6	0	0	0
5	0	FM3 EPC switch	Yes	DOWN	No	2	6	0	0	0
6	0	FM2 EPC switch	Yes	DOWN	No	2	6	0	0	0
7	0	FM1 EPC switch	Yes	DOWN	No	2	6	0	0	0
8		Other SC EPC switch	Yes	UP	No	2	6	351356399	351310095	1672664
9		Local SC 4-port switch	Yes	UP	No	2	6	351310031	351356399	3345688

Rule	Rule_name	Match_ctr	Pol_en	Pol_idx	inProfileBytes	outOfProfileBytes
------	-----------	-----------	--------	---------	----------------	-------------------

Useful commands

Show hardware access-list tcam region

Show run | inc TCAM"-----No output means TCAM is set to default settings.

Useful links

[Nexus 9000 TCAM Carving](#)