



## **Release Notes for Cisco ASR 920 Series Aggregation Services Router, Cisco IOS XE Bengaluru 17.6.x**

**First Published:** 2021-07-29

**Last Modified:** 2024-04-05

### **Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
<http://www.cisco.com>  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 527-0883





## CONTENTS

---

### CHAPTER 1

#### **Introduction 1**

Cisco ASR 920 Series Routers Overview	2
Feature Navigator	2
Feature Matrix	2
Software Licensing Overview	2
Determining the Software Version	3
Upgrading to a New Software Release	4
Supported HoFPGA and ROMMON Versions	4
Restrictions and Limitations	10
Documentation Updates	11
Additional References	12

---

### CHAPTER 2

#### **What's New in Cisco IOS XE Bengaluru 17.6.x 13**

What's New in Hardware for Cisco IOS XE Bengaluru 17.6.7	13
What's New in Software for Cisco IOS XE Bengaluru 17.6.7	13
What's New in Hardware for Cisco IOS XE Bengaluru 17.6.6a	14
What's New in Software for Cisco IOS XE Bengaluru 17.6.6a	14
What's New in Hardware for Cisco IOS XE Bengaluru 17.6.6	14
What's New in Software for Cisco IOS XE Bengaluru 17.6.6	14
What's New in Hardware for Cisco IOS XE Bengaluru 17.6.5	14
What's New in Software for Cisco IOS XE Bengaluru 17.6.5	14
What's New in Hardware for Cisco IOS XE Bengaluru 17.6.4	14
What's New in Software for Cisco IOS XE Bengaluru 17.6.4	14
What's New in Hardware for Cisco IOS XE Bengaluru 17.6.3	14
What's New in Software for Cisco IOS XE Bengaluru 17.6.3	15
What's New in Hardware for Cisco IOS XE Bengaluru 17.6.2	15

What's New in Software for Cisco IOS XE Bengaluru 17.6.2 15  
 What's New in Hardware for Cisco IOS XE Bengaluru 17.6.1 15  
 What's New in Software for Cisco IOS XE Bengaluru 17.6.1 15

**CHAPTER 3**

**Caveats 19**

Open Caveats - Cisco IOS XE Bengaluru 17.6.7 20  
 Resolved Caveats – Cisco IOS XE Bengaluru 17.6.7 20  
 Open Caveats - Cisco IOS XE Bengaluru 17.6.6a 20  
 Resolved Caveats – Cisco IOS XE Bengaluru 17.6.6a 20  
 Open Caveats – Cisco IOS XE Bengaluru 17.6.6 20  
 Resolved Caveats – Cisco IOS XE Bengaluru 17.6.6 20  
 Open Caveats – Cisco IOS XE Bengaluru 17.6.5 21  
 Open Caveats – Cisco IOS XE Bengaluru 17.6.5 - Platform Independent 22  
 Resolved Caveats – Cisco IOS XE Bengaluru 17.6.5 22  
 Resolved Caveats – Cisco IOS XE Bengaluru 17.6.5 - Platform Independent 22  
 Open Caveats – Cisco IOS XE Bengaluru 17.6.4 23  
 Open Caveats – Cisco IOS XE Bengaluru 17.6.4 - Platform Independent 23  
 Resolved Caveats – Cisco IOS XE Bengaluru 17.6.4 23  
 Resolved Caveats – Cisco IOS XE Bengaluru 17.6.4 - Platform Independent 23  
 Open Caveats – Cisco IOS XE Bengaluru 17.6.3 24  
 Open Caveats – Cisco IOS XE Bengaluru 17.6.3 - Platform Independent 24  
 Resolved Caveats – Cisco IOS XE Bengaluru 17.6.3 24  
 Resolved Caveats – Cisco IOS XE Bengaluru 17.6.3 - Platform Independent 24  
 Open Caveats – Cisco IOS XE Bengaluru 17.6.2 25  
 Resolved Caveats – Cisco IOS XE Bengaluru 17.6.2 25  
 Resolved Caveats – Cisco IOS XE Bengaluru 17.6.2 - Platform Independent 25  
 Open Caveats – Cisco IOS XE Bengaluru 17.6.1 25  
 Resolved Caveats – Cisco IOS XE Bengaluru 17.6.1 26  
 Cisco Bug Search Tool 27



# CHAPTER 1

## Introduction

---

This release notes contain information about the Cisco ASR 920 Series Aggregation Services Routers, provides new and changed information for these routers, hardware support, limitations and restrictions, and caveats.



---

**Note** Explore the [Content Hub](#), the all new portal that offers an enhanced product documentation experience.

- Use faceted search to locate content that is most relevant to you.
- Create customized PDFs for ready reference.
- Benefit from context-based recommendations.

Get started with the Content Hub at [content.cisco.com](https://content.cisco.com) to craft a personalized documentation experience.

Do provide feedback about your experience with the Content Hub.

---

This release notes provides information for these variants of the Cisco ASR 920 Series Routers:

- ASR-920-12CZ-A
- ASR-920-12CZ-D
- ASR-920-4SZ-A
- ASR-920-4SZ-D
- ASR-920-10SZ-PD
- ASR-920-24SZ-IM
- ASR-920-24SZ-M
- ASR-920-24TZ-M
- ASR-920-12SZ-IM
- ASR-920-12SZ-A
- ASR-920-12SZ-D
- ASR 920-8S4Z-PD

Starting with Cisco IOS XE Bengaluru Release 17.4.1, Cisco ASR-920-24SZ-IM, Cisco ASR-920-24SZ-M, Cisco ASR-920-24TZ-M, Cisco ASR 920-10SZ-PD, Cisco ASR-920-12CZ-A/D, and Cisco ASR-920-4SZ-A/D routers are auto upgraded to ROMMON version 15\_6\_44r\_s.

- [Cisco ASR 920 Series Routers Overview, on page 2](#)
- [Feature Navigator, on page 2](#)
- [Feature Matrix, on page 2](#)
- [Software Licensing Overview, on page 2](#)
- [Determining the Software Version, on page 3](#)
- [Upgrading to a New Software Release, on page 4](#)
- [Supported HoFPGA and ROMMON Versions, on page 4](#)
- [Restrictions and Limitations, on page 10](#)
- [Documentation Updates, on page 11](#)
- [Additional References, on page 12](#)

## Cisco ASR 920 Series Routers Overview

The Cisco ASR 920 Series Aggregation Services Routers provide a comprehensive and scalable set of Layer 2 and Layer 3 VPN services in a compact package. They are temperature-hardened, small form factor, with high throughput and low power consumption ideal for mobile backhaul, business services and residential voice, video, and data ("triple-play") applications.

## Feature Navigator

Use the Cisco Feature Navigator to find information about feature, platform, and software image support. To access the Cisco Feature Navigator, go to <http://www.cisco.com/go/cfn>. An account on cisco.com is not required.

## Feature Matrix

The feature matrix lists the features supported for each platform. For more information, see the [Cisco ASR 920 Series Aggregation Services Routers Feature Compatibility Matrix](#).

The cumulative [Feature Compatibility Release Matrix](#) is available on Content Hub.

## Software Licensing Overview

Starting with Cisco IOS XE Cupertino 17.7.1, PAK licenses are no longer available. When you purchase the Cisco IOS XE Cupertino 17.7.1 release or later, Smart Licensing is enabled by default. We recommend that you move to Smart Licensing before upgrading to Cisco IOS XE Cupertino 17.7.1 or a higher release, for a seamless experience.

If you are using Cisco IOS XE Bengaluru 17.6.1 or an earlier release version, Smart Licensing is not enabled by default. To enable Smart Licensing, see [Software Activation Configuration Guide \(Cisco IOS XE ASR 920 Routers\)](#).

The router offers the following base licenses:

- Metro Services
- Metro IP Services
- Advanced Metro IP access
  - SDM Video Template

**Table 1: Cisco ASR 920 Software Licenses Feature Set**

Metro Services	Metro IP Services	Metro Aggregation Services
—	Includes all features in Metro Services	Includes all features in Metro IP Services
QoS, with deep buffers and hierarchical QoS (HQOS)	IP routing (RIP, OSPF, EIGRP, BGP, IS-IS)	MPLS (LDP and VPN)
Layer 2: 802.1d, 802.1q	PIM (SM, DM, SSM), SSM mapping	MPLS TE and FRR
Ethernet Virtual Circuit (EVC)	BFD	MPLS OAM
Ethernet OAM (802.1ag, 802.3ah)	Multi-VRF CE (VRF lite) with service awareness (ARP, ping, SNMP, syslog, trace-route, FTP, TFTP)	MPLS-TP
Multiple Spanning Tree (MST) and Resilient Ethernet Protocol (REP)	IEEE 1588-2008 Ordinary Slave Clock and Transparent Clock	Pseudowire emulation (EoMPLS, CESoPSN, and SAToP)
Synchronous Ethernet	—	VPLS and HVPLS
IPv4 and IPv6 host connectivity	—	Pseudowire redundancy
—	—	MR-APS and mLACP

The router offers the following additional feature licenses:

- ATM
- IEEE 1588-2008 Boundary Clock/Master Clock
- OC-x Port License

## Determining the Software Version

Use the following commands to verify your software version:

- Consolidated Package— **show version**

**Table 2: ROMMON Version**

PIDs	ROMMON
ASR-920-12SZ-A , ASR-920-12SZ-D	15.6(46r)S

PIDs	ROMMON
ASR-920-12SZ-IM	15.6(46r)S
ASR-920-12CZ-A, ASR-920-12CZ-D, ASR-920-4SZ-A, ASR-920-4SZ-D, ASR-920-10SZ-PD, ASR-920-24SZ-IM, ASR-920-24SZ-M, ASR-920-24TZ-M, and ASR920-8S4Z-PD	15.6(48r)S

## Upgrading to a New Software Release

Only the latest consolidated packages can be downloaded from Cisco.com; users who want to run the router using individual subpackages must first download the image from Cisco.com and extract the individual subpackages from the consolidated package.

For information about upgrading to a new software release, see the [Upgrading the Software on the Cisco ASR 920 Series Routers](#).

### Upgrading the FPD Firmware

FPD Firmware packages are bundled with the software package. FPD upgrade is automatically performed on the router.

If you like to manually change the FPD Firmware software, use the **upgrade hw-module subslot 0/0 fpd bundle** to perform FPD firmware upgrade.

## Supported HoFPGA and ROMMON Versions

The tables below list the HoFPGA and ROMMON version of the software releases.

**Table 3: HoFPGA and ROMMON Versions for the Cisco ASR-920-12CZ-A, ASR-920-12CZ-D, ASR-920-4SZ-A, ASR-920-4SZ-D, ASR-920-10SZ-PD, and ASR 920-8S4Z-PD**

Release	HoFPGA Version	ROMMON Version
Cisco IOS XE Gibraltar 16.12.1	0X00040043	15.6(32r)S
Csico IOS XE Gibraltar 16.12.2a	0x00040043 (BFD/default template) 0x00020009 (Netflow template)	15.6(32r)S
Cisco IOS XE Amsterdam 17.1.x	0X00040043 (BFD/default template) 0x00020009 (Netflow template)	15.6(32r)S
Cisco IOS XE Amsterdam 17.3.1	0X00020009	15.6(43r)S



Release	HoFPGA Version	ROMMON Version
Cisco IOS XE Amsterdam 17.3.2	0X00020009	15.6(43r)S
Cisco IOS XE Bengaluru 17.4.1	0X00040044 (BFD/default template)	15.6(44r)S
Cisco IOS XE Bengaluru 17.5.1	0X00040044 (BFD/default template)	15.6(44r)S
Cisco IOS XE Bengaluru 17.6.1	0X00040044	15.6(48r)S
Cisco IOS XE Bengaluru 17.6.2	0X00040044	15.6(48r)S
Cisco IOS XE Bengaluru 17.6.3	0X00040044	15.6(48r)S
Cisco IOS XE Bengaluru 17.6.4	0X00040044	15.6(48r)S
Cisco IOS XE Bengaluru 17.6.5	0X00040044	15.6(48r)S
Cisco IOS XE Bengaluru 17.6.6	0X00040044	15.6(48r)S
Cisco IOS XE Bengaluru 17.6.6a	0X00040044	15.6(48r)S
Cisco IOS XE Bengaluru 17.6.7	0X00040044	15.6(48r)S

**Table 4: HoFPGA and ROMMON Versions for the Cisco ASR-920-24SZ-IM, ASR-920-24SZ-M, and ASR-920-24TZ-M**

Release	HoFPGA Version	ROMMON Version
Cisco IOS XE Gibraltar 16.12.1	0X00030014	15.6(32r)S
Cisco IOS XE Gibraltar 16.12.2a	0x00030014 (BFD/default template) 0x00030014 (Netflow template)	15.6(32r)S
Cisco IOS XE Amsterdam 17.1.x	0x00030014 (BFD/default template) 0x00030014 (Netflow template)	15.6(32r)S
Cisco IOS XE Amsterdam 17.3.1	0X00030014	15.6(43r)S
Cisco IOS XE Amsterdam 17.3.2	0X00030014	15.6(43r)S
Cisco IOS XE Bengaluru 17.4.1	0X00030016	15.6(44r)S
Cisco IOS XE Bengaluru 17.5.1	0X00040019	15.6(44r)S
Cisco IOS XE Bengaluru 17.6.1	0X0004001b	15.6(48r)S
Cisco IOS XE Bengaluru 17.6.2	0X0004001b	15.6(48r)S
Cisco IOS XE Bengaluru 17.6.3	0X0004001b	15.6(48r)S

Release	HoFPGA Version	ROMMON Version
Cisco IOS XE Bengaluru 17.6.4	0X0004001b	15.6(48r)S
Cisco IOS XE Bengaluru 17.6.5	0X0004001b	15.6(48r)S
Cisco IOS XE Bengaluru 17.6.6	0X0004001b	15.6(48r)S
Cisco IOS XE Bengaluru 17.6.6a	0X0004001b	15.6(48r)S
Cisco IOS XE Bengaluru 17.6.7	0X0004001b	15.6(48r)S

**Table 5: HoFPGA and ROMMON Versions for the Cisco ASR-920-12SZ-IM**

Release	HoFPGA Version	ROMMON Version
Cisco IOSXE Gibraltar 16.12.1	0X0003001B	15.6(24r)S
Cisco IOS XE Gibraltar 16.12.2a	0x0003001B (BFD/default template) 0x00020008 (Netflow template)	15.6(24r)S
Cisco IOS XE Amsterdam 17.1.x	0x0003001B (BFD/default template) 0x00020008 (Netflow template)	15.6(24r)S
Cisco IOS XE Amsterdam 17.3.1	0X0003001b	15.6(43r)S
Cisco IOS XE Amsterdam 17.3.2	0X0003001b	15.6(43r)S
Cisco IOS XE Bengaluru 17.4.1	0X0003001e	15.6(43r)S
Cisco IOS XE Bengaluru 17.5.1	0X0003001e	15.6(43r)S
Cisco IOS XE Bengaluru 17.6.1	0X0003001e	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.2	0X0003001e	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.3	0X0003001e	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.4	0X0003001e	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.5	0X0003001e	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.6	0X0003001e	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.6a	0X0003001e	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.7	0X0003001e	15.6(46r)S

**Table 6: HoFPGA and ROMMON Versions for the Cisco ASR-920-12SZ-A and ASR-920-12SZ-D**

Release	HoFPGA Version	ROMMON Version
Cisco IOS XE Gibraltar 16.12.1	0X00010039	15.6(29r)S
Cisco IOS XE Gibraltar 16.12.2a	0x00010039 (BFD/default template) 0x10000007 (Netflow template)	15.6(29r)S
Cisco IOS XE Amsterdam 17.1.x	0x00010039 (BFD/default template) 0x10000007 (Netflow template)	15.6(29r)S
Cisco IOS XE Amsterdam 17.3.1	0X10000008	15.6(43r)S
Cisco IOS XE Amsterdam 17.3.2	0X10000008	15.6(43r)S
Cisco IOS XE Bengaluru 17.4.1	0X00010040 (BFD/default template)	15.6(43r)S
Cisco IOS XE Bengaluru 17.5.1	0X10000008	15.6(43r)S
Cisco IOS XE Bengaluru 17.6.1	0X10000008	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.2	0X00020043	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.3	0X00020043	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.4	0X00020043	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.5	0X00020043	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.6	0X00020043	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.6a	0X00020043	15.6(46r)S
Cisco IOS XE Bengaluru 17.6.7	0X00020043	15.6(46r)S

**Table 7: IM FPGA Versions for the Cisco ASR-920-24SZ-IM**

Release	Gigabit Ethernet Interface Module (Phase 1) FPGA	Gigabit Ethernet Interface Module (Phase2) FPGA	8 T1/E1	16 T1/E1	32 T1/E1
Cisco IOS XE Amsterdam 17.1.x	0.49	69.24	0.54	0.54	0.46
Cisco IOS XE Amsterdam 17.3.1	0.49	69.24	0.54	0.54	0.46

Release	Gigabit Ethernet Interface Module (Phase 1) FPGA	Gigabit Ethernet Interface Module (Phase2) FPGA	8 T1/E1	16 T1/E1	32 T1/E1
Cisco IOS XE Amsterdam 17.3.2	0.75	N/A	N/A	0.54	0.46
Cisco IOS XE Bengaluru 17.4.1	0.75	N/A	N/A	0.54	0.46
Cisco IOS XE Bengaluru 17.5.1	0.75	N/A	N/A	0.54	0.46
Cisco IOS XE Bengaluru 17.6.1	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.2	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.3	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.4	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.5	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.6	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.6a	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.7	0.75	69.24	0.54	0.54	0.46

Table 8: IM FPGA Versions for the Cisco ASR-920-12SZ-IM

Release	Gigabit Ethernet Interface Module (Phase 1) FPGA	Gigabit Ethernet Interface Module (Phase2) FPGA	8 T1/E1	16 T1/E1	32 T1/E1
Cisco IOS XE Amsterdam 17.1.x	0.49	69.24	0.54	0.54	0.46
Cisco IOS XE Amsterdam 17.3.1	0.49	69.24	0.54	0.54	0.46
Cisco IOS XE Amsterdam 17.3.2	0.75	N/A	N/A	0.54	0.46
Cisco IOS XE Bengaluru 17.4.1	0.75	N/A	N/A	0.54	0.46
Cisco IOS XE Bengaluru 17.5.1	0.75	N/A	N/A	0.54	0.46
Cisco IOS XE Bengaluru 17.6.1	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.2	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.3	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.4	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.5	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.6	0.75	69.24	0.54	0.54	0.46
Cisco IOS XE Bengaluru 17.6.6a	0.75	69.24	0.54	0.54	0.46

Release	Gigabit Ethernet Interface Module (Phase 1) FPGA	Gigabit Ethernet Interface Module (Phase2) FPGA	8 T1/E1	16 T1/E1	32 T1/E1
Cisco IOS XE Bengaluru 17.6.7	0.75	69.24	0.54	0.54	0.46

## Restrictions and Limitations



**Note** The error message "PLATFORM-1-NOSPACE: SD bootflash : no space alarm assert" may occur in the following scenarios:

- Any sector of SD Card gets corrupted
- Improper shut down of router
- power outage.

This issue is observed on platforms which use EXT2 file systems.

We recommend performing a reload of the router. As a result, above alarm will not be seen during the next reload due to FSCK(file systems check) execution.

However, If the error persists after a router reload, we recommend to format the bootflash or FSCK manually from IOS.

- Embedded Packet Capture (EPC) is not supported on ASR 920 routers.
- The **default** *command-name* command is used to default the parameters under that interface. However, when speed is configured on the interface, the following error is displayed:  

```
Speed is configured. Remove speed configuration before enabling auto-negotiation
```
- For VCoP, only SFP-T3F-SATOP-I is supported.
- Adding or deleting the Trunk Ethernet flow points (TEFPs) with scaled bridge-domain, without delay causes the Cisco ASR 920 Series router to crash.
- Virtual services should be deactivated and uninstalled before performing replace operations.
- The Cisco ASR920 Series Routers no longer support the controller and nid-controller commands for the Cisco ME1200 switch.
- The following interface modules (IMs) do not require the activation command for IM boot up, provided no other IM is activated in subslot 0/1 before.

However, if an IM was activated in the system earlier, deactivate the previously-activated IM before inserting a new IM in system.

- 16-Port T1/E1 Interface Module

- 32-Port T1/E1 Interface Module
  - 8-Port T1/E1 Interface Module
  - 4-port OC3/STM-1 (OC-3) or 1-port OC12/STM-4 (OC-12) Interface Module
  - 14-Port Serial Interface Module
  - 6-Port E and M Interface Module
  - 4-Port C37.94 Interface Module
- RS422 works on ports from 0 to 7 only.
  - The frame drops may occur for packets with packet size of less than 100 bytes, when there is a line rate of traffic over all 1G or 10G interfaces available in the system. This restriction is applicable only on RSP2 module and ASR 920 platform, and is not applicable for RSP3 module.
  - MPLS VC label packet with time-to-live (TTL) value of 2 is dropped at egress MPLS PE device due to ASIC limitations. During PHP process, MPLS TTL value for the VC label is decremented by one with implicit-null. The VC label-related TTL value is set to 255 while imposing the VC label due to multiple VC switching scenarios.

Use the **no mpls ip propagate-ttl** command as the Short Pipe mode for the required label.

- Interface naming is from right to left. For more information, see the Cisco ASR 920 Software Configuration Guide .
- Packet size greater than 1460 is not supported over IPsec Tunnel.
- Minimal traffic drop might be seen for a moment when higher rate traffic is sent through the IPsec tunnels for the first time.
- One Ternary Content-Addressable Memory (TCAM) entry is utilized for Segment Routing Performance Measurement. This is required for the hardware timestamping to function.
- While performing an auto upgrade of ROMMON, only primary partition is upgraded. Use the **upgrade rom-mon filename** command to upgrade the secondary partition of the ROMMON. However, the router can be reloaded during the next planned reload to complete the secondary ROMMON upgrade.
- Some router models are not fully compliant with all IETF guidelines as exemplified by running the pyang tool with the lintflag. The errors and warnings exhibited by running the pyang tool with the lint flag are currently non-critical as they do not impact the semantic of the models or prevent the models from being used as part of the toolchains. A script is provided, **check-models.sh**, which runs pyang with lint validation enabled, but ignoring certain errors. This allows the developer to determine what issues may be present.
- If IPv6 Global IP is configured as the BFD peer, and if the interface goes down, a VRRP flap may occur. This may occur because, VRRP works on the basis of Link-local IP and not global IP. As a result, VRRP flaps on the previously backed up device and prints a DAD message.

## Documentation Updates

IPv4 Unicast Generic Routing Encapsulation Tunnel Overview is now available in the [IP Routing: GRE Configuration Guide, Cisco IOS XE 17 \(Cisco ASR 920 Series\)](#). The chapter is moved from the MPLS: Layer 3 VPNs Configuration Guide.

# Additional References

## Product Information

- [Cisco ASR 920 Series Aggregation Services Router Data Sheets](#)

## Hardware Installation Guides

- [Cisco ASR 920 Series Aggregation Services Router Hardware Guides](#)

## Software Configuration Guides

- [Cisco ASR 920 Series Aggregation Services Router Configuration Guides](#)

## Regulatory Compliance and Safety Information

- [Regulatory Compliance and Safety Information for the Cisco ASR 920 Series Aggregation Services Routers](#)

## Field Notices and Bulletins

- Field Notices—We recommend that you view the field notices for this release to determine whether your software or hardware platforms are affected. You can find field notices at [http://www.cisco.com/en/US/support/tsd\\_products\\_field\\_notice\\_summary.html](http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html).
- Bulletins—You can find bulletins at [http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod\\_literature.html](http://www.cisco.com/en/US/products/sw/iosswrel/ps5012/prod_literature.html).

## MIB Support

To view supported MIB, go to <http://tools.cisco.com/ITDIT/MIBS/MainServlet>.

## Accessibility Features in the Cisco ASR 920 Series Routers

For a list of accessibility features in Cisco ASR 920 Series Routers, see the [Voluntary Product Accessibility Template \(VPAT\)](#) on the Cisco website, or contact [accessibility@cisco.com](mailto:accessibility@cisco.com).

All product documents are accessible except for images, graphics, and some charts. If you would like to receive the product documentation in audio format, braille, or large print, contact [accessibility@cisco.com](mailto:accessibility@cisco.com).

## End-of-Life and End-of-Sale Notices

For End-of-Life and End-of-Sale Notices for the Cisco ASR 920 Series Routers, see <http://www.cisco.com/c/en/us/products/routers/asr-920-series-aggregation-services-router/eos-eol-notice-listing.html>.





## CHAPTER 2

# What's New in Cisco IOS XE Bengaluru 17.6.x

This chapter describes the new hardware and software features supported on the Cisco ASR 920 Series routers in Cisco IOS XE Bengaluru 17.6.x.

For information on features supported for each release, see [Feature Compatibility Matrix](#).

- [What's New in Hardware for Cisco IOS XE Bengaluru 17.6.7, on page 13](#)
- [What's New in Software for Cisco IOS XE Bengaluru 17.6.7, on page 13](#)
- [What's New in Hardware for Cisco IOS XE Bengaluru 17.6.6a, on page 14](#)
- [What's New in Software for Cisco IOS XE Bengaluru 17.6.6a, on page 14](#)
- [What's New in Hardware for Cisco IOS XE Bengaluru 17.6.6, on page 14](#)
- [What's New in Software for Cisco IOS XE Bengaluru 17.6.6, on page 14](#)
- [What's New in Hardware for Cisco IOS XE Bengaluru 17.6.5, on page 14](#)
- [What's New in Software for Cisco IOS XE Bengaluru 17.6.5, on page 14](#)
- [What's New in Hardware for Cisco IOS XE Bengaluru 17.6.4, on page 14](#)
- [What's New in Software for Cisco IOS XE Bengaluru 17.6.4, on page 14](#)
- [What's New in Hardware for Cisco IOS XE Bengaluru 17.6.3, on page 14](#)
- [What's New in Software for Cisco IOS XE Bengaluru 17.6.3, on page 15](#)
- [What's New in Hardware for Cisco IOS XE Bengaluru 17.6.2, on page 15](#)
- [What's New in Software for Cisco IOS XE Bengaluru 17.6.2, on page 15](#)
- [What's New in Hardware for Cisco IOS XE Bengaluru 17.6.1, on page 15](#)
- [What's New in Software for Cisco IOS XE Bengaluru 17.6.1, on page 15](#)

## What's New in Hardware for Cisco IOS XE Bengaluru 17.6.7

There are no hardware features for this release.

## What's New in Software for Cisco IOS XE Bengaluru 17.6.7

There are no new software features in this release.

## What's New in Hardware for Cisco IOS XE Bengaluru 17.6.6a

There are no hardware features for this release.

## What's New in Software for Cisco IOS XE Bengaluru 17.6.6a

There are no new features in this release. This release provides a fix for CSCwh87343: Cisco IOS XE Software Web UI Privilege Escalation Vulnerability. For more information, see [cisco-sa-iosxe-webui-privesc-j22SaA4z](#).

## What's New in Hardware for Cisco IOS XE Bengaluru 17.6.6

There are no new hardware features in this release.

## What's New in Software for Cisco IOS XE Bengaluru 17.6.6

There are no new software features in this release.

## What's New in Hardware for Cisco IOS XE Bengaluru 17.6.5

There are no new hardware features in this release.

## What's New in Software for Cisco IOS XE Bengaluru 17.6.5

There are no new software features in this release.

## What's New in Hardware for Cisco IOS XE Bengaluru 17.6.4

There are no new hardware features in this release.

## What's New in Software for Cisco IOS XE Bengaluru 17.6.4

There are no new software features in this release.

## What's New in Hardware for Cisco IOS XE Bengaluru 17.6.3

There are no new hardware features in this release.

## What's New in Software for Cisco IOS XE Bengaluru 17.6.3

There are no new software features in this release.

## What's New in Hardware for Cisco IOS XE Bengaluru 17.6.2

There are no new hardware features in this release.

## What's New in Software for Cisco IOS XE Bengaluru 17.6.2

There are no new software features in this release.

## What's New in Hardware for Cisco IOS XE Bengaluru 17.6.1

There are no new hardware features in this release.

## What's New in Software for Cisco IOS XE Bengaluru 17.6.1

Feature	Description
<b>First Hop Redundancy Protocols</b>	
<a href="#">Support for BFD, sub-second fast hello for VRRPv3 convergence and re-convergence</a>	This feature supports VRRP failover such that the fault is detected by the VRRP-BFD client within the configured value – when the connection to the remote interface IP address fails.
<b>IP Routing</b>	
<a href="#">Establish GRE Tunnel over VRF Routes</a>	This feature establishes GRE tunnels over Virtual Route Forward (VRF) routes.
<b>MPLS Layer 2 VPNs</b>	
<a href="#">Remote LFA for MLDP</a>	Remote Loop-Free Alternate (RLFA) based Fast Reroute (FRR) improves LFA coverage. When used with Multicast Label Distribution Protocol (MLDP) for IPv4, there is no need for an extra protocol in the control plane.
<b>Network Management</b>	

Feature	Description
<a href="#">Ingress and Egress Flexible NetFlow</a>	Flexible NetFlow allows you to monitor the traffic from access circuit on an L2VPN and L3VPN network. In addition to monitoring traffic in routed and ethernet service interfaces, you can now monitor traffic in VRF enabled L2 VFI (virtual forwarding interfaces) and cross-connect services.
<b>Programmability</b>	
YANG Model Support for <b>show mpls tr tunnel</b> Command	This feature enables you to verify the <b>show mpls traffic engineering tunnel</b> command to check the status from YANG models.
YANG Model Support for RSVP Commands	You can use the <b>interface BDI 10</b> and <b>ip RSVP bandwidth percent 4</b> commands to configure the RSVP bandwidth on a BDI interface from YANG. You can configure, modify, and verify different bandwidth values using these commands.
YANG Model Support for IPSLA Operating Model for Y1731	You can check the history interval statistics of delay operations like DMM, DMMv1 and IDM, and loss operations like LMM and SLM using the NETCONF-YANG command to enable YANG data collection.
YANG Model Support for QoS Overhead Accounting	QoS Overhead Accounting feature enables a particular port to consider a particular number of bits that are removed from the packet when the egress packet is re-edited. The traffic scheduler allows more bits than the configured rate at the port, without exceeding the number of bytes that is configured on a port.  YANG QOS Overhead accounting configuration model supports the configuration on the router accounting on router from YANG/NETCONF protocol.
YANG Model Support for Alarm Profile Configurations	This feature enables you to configure the alarm profile on the interface through native YANG models that run on Cisco IOS XE.
YANG Model Support for Shared Risk Link Groups (SRLG) Group Identification (GID) Configurations	Shared Risk Link Groups (SRLG) Group Identification (GID) configurations can be enabled on YANG using the <b>srlg gid</b> command. Multiple groups and interfaces can be enabled on the interface mode.
<b>Segment Routing</b>	
<a href="#">EVPN-IRB DHCP v4 and v6 Relay over Segment Routing</a>	This feature introduces a specialised implementation of DHCP packets to support DHCPv4 and DHCPv6 in an EVPN Fabric with Distributed Anycast Gateways (DAGs) on the same Virtual Routing and Forwarding (VRF). It also avoids DHCP discovery packet floods across the fabric.  The flooding suppression feature is also enhanced to intercept multicast or broadcast DHCP packets when DHCP relay is configured on the DAG to perform the required action and localize the scope of the service.

Feature	Description
<a href="#">IS-IS Flexible Algorithm Include Affinity Support</a>	This feature supports "include-any" and "include-all" affinities in IS-IS. Prior to Cisco IOS XE Bengaluru 17.6.1 release, only Flexible Algorithm affinity "exclude-any" was supported.
<a href="#">OSPF Flexible Algorithm (Ph2): Topology-Independent Loop-Free Alternate (TI-LFA) path</a>	This feature allows you to configure the Loop-Free Alternate (LFA) and TI-LFA backup or repair paths for a Flexible Algorithm. The backup path is computed based on the constraints and metrics of the primary path. Prior to Cisco IOS XE Bengaluru 17.6.1, OSPF Flexible Algorithm supported only the primary path.
<a href="#">SR-PCE: Enabling SR PM Delay or Liveness for PCE-Initiated Policies</a>	This feature enables the Path Computation Element (PCE) that can provision a Segment Routing Traffic Engineering (SR-TE) policy to mitigate link congestion. Prior to this release, you could only enable PM link and delay measurement using CLI-based policies. Starting with this release, you can also use PCE to enable PM link and delay measurement.
<a href="#">Stitching of Subnet Route from EVPN to L3VPN</a>	This feature introduces the collapsed spine and border leaf node in the network topology of single homing DAGs with symmetric IRB, inter-subnet layer 3 traffic within fabric and inter-subnet layer 3 stitching through layer 3 border gateway. The hosts participating in fabric IRB are directly attached with the collapsed spine and border leaf node.
<b>System Management</b>	
<a href="#">Cisco Secure Development Lifecycle—Factory Reset</a>	<p>This feature removes all the customer-specific data that stored on the device since the time of its shipping. Data erased includes configurations, log files, boot variables, core files, and credentials like FIPS-related keys. Cisco Secure Development Lifecycle (CSDL) is a repeatable and measurable process designed to increase Cisco product resiliency and trustworthiness.</p> <p>The following new commands are introduced:</p> <ul style="list-style-type: none"> <li>• <b>factory-reset all</b></li> <li>• <b>factory-reset keep-licensing-info</b></li> <li>• <b>factory-reset all secure 3-pass DoD 5220.22-M</b></li> </ul> <p>For information on the commands, <a href="#">Cisco IOS Configuration Fundamentals Command Reference</a>.</p>
<b>Time Division Multiplexing</b>	

Feature	Description
Support for E1 framed Smart TPOp pluggable	<p>You can configure the following features for E1 in framed and unframed modes:</p> <ul style="list-style-type: none"> <li>• Loopback, framing, line code encoding, cable length, and jitter buffer</li> <li>• BERT</li> <li>• Performance monitoring counters and alarms</li> <li>• Alarm profiling</li> <li>• Clock recovery modes</li> </ul> <p>These features that are configured on framed and unframed E1 interfaces help you to monitor the traffic and troubleshoot errors or failures efficiently.</p>
Support for T1 framed Smart TPOp pluggable	<p>You can configure the following features for T1 in framed and unframed modes:</p> <ul style="list-style-type: none"> <li>• Loopback, framing, line code encoding, cable length, and jitter buffer</li> <li>• BERT</li> <li>• Performance monitoring counters and alarms</li> <li>• Alarm profiling</li> <li>• Clock recovery modes</li> </ul> <p>These features that are configured on framed and unframed T1 interfaces help you to monitor the traffic and troubleshoot errors or failures efficiently.</p>
Support for TSoP SSFP Dejitter Buffer Tuning	TSoP SSFP Dejitter Buffer Tuning is applicable only for T1 smart SFP.
<b>Upgrading the Software on the Cisco ASR 920 Series Routers</b>	
Upgrading Power Supply Monitoring Firmware	This feature allows you to manually upgrade the firmware of the power supply monitoring device in a router. The firmware upgrade reduces unplanned hardware-related downtime caused by input voltage transients during a power outage.

YANG Data Models—For the list of Cisco IOS XE YANG models available with this release, navigate to <https://github.com/YangModels/yang/tree/master/vendor/cisco/xe/1761>.

Revision statements embedded in the YANG files indicate if there has been a model revision. The README.md file in the same GitHub location highlights changes that have been made in the release.

For more information, see *Programmability Configuration Guide, Cisco IOS XE Bengaluru 17.6.x*.



## CHAPTER 3

# Caveats

This chapter describes open and resolved severity 1 and 2 caveats and select severity 3 caveats:

- The “Open Caveats” sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.
- The “Resolved Caveats” sections list caveats resolved in a specific release, but open in previous releases.

The bug IDs are sorted alphanumerically.



**Note** The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- [Open Caveats - Cisco IOS XE Bengaluru 17.6.7, on page 20](#)
- [Resolved Caveats – Cisco IOS XE Bengaluru 17.6.7, on page 20](#)
- [Open Caveats - Cisco IOS XE Bengaluru 17.6.6a, on page 20](#)
- [Resolved Caveats – Cisco IOS XE Bengaluru 17.6.6a, on page 20](#)
- [Open Caveats – Cisco IOS XE Bengaluru 17.6.6, on page 20](#)
- [Resolved Caveats – Cisco IOS XE Bengaluru 17.6.6, on page 20](#)
- [Open Caveats – Cisco IOS XE Bengaluru 17.6.5, on page 21](#)
- [Open Caveats – Cisco IOS XE Bengaluru 17.6.5 - Platform Independent, on page 22](#)
- [Resolved Caveats – Cisco IOS XE Bengaluru 17.6.5, on page 22](#)
- [Resolved Caveats – Cisco IOS XE Bengaluru 17.6.5 - Platform Independent, on page 22](#)
- [Open Caveats – Cisco IOS XE Bengaluru 17.6.4, on page 23](#)
- [Open Caveats – Cisco IOS XE Bengaluru 17.6.4 - Platform Independent, on page 23](#)
- [Resolved Caveats – Cisco IOS XE Bengaluru 17.6.4, on page 23](#)
- [Resolved Caveats – Cisco IOS XE Bengaluru 17.6.4 - Platform Independent, on page 23](#)
- [Open Caveats – Cisco IOS XE Bengaluru 17.6.3, on page 24](#)
- [Open Caveats – Cisco IOS XE Bengaluru 17.6.3 - Platform Independent, on page 24](#)
- [Resolved Caveats – Cisco IOS XE Bengaluru 17.6.3, on page 24](#)
- [Resolved Caveats – Cisco IOS XE Bengaluru 17.6.3 - Platform Independent, on page 24](#)
- [Open Caveats – Cisco IOS XE Bengaluru 17.6.2, on page 25](#)
- [Resolved Caveats – Cisco IOS XE Bengaluru 17.6.2, on page 25](#)
- [Resolved Caveats – Cisco IOS XE Bengaluru 17.6.2 - Platform Independent, on page 25](#)

- [Open Caveats – Cisco IOS XE Bengaluru 17.6.1, on page 25](#)
- [Resolved Caveats – Cisco IOS XE Bengaluru 17.6.1, on page 26](#)
- [Cisco Bug Search Tool, on page 27](#)

## Open Caveats - Cisco IOS XE Bengaluru 17.6.7

There are no open caveats in this release.

## Resolved Caveats – Cisco IOS XE Bengaluru 17.6.7

Identifier	Headline
<a href="#">CSCwi75499</a>	Lost CEM circuit configuration after reboot
<a href="#">CSCwj06370</a>	Serial cease traffic when configuring module other port

## Open Caveats - Cisco IOS XE Bengaluru 17.6.6a

There are no open caveats in this release.

## Resolved Caveats – Cisco IOS XE Bengaluru 17.6.6a

Identifier	Headline
<a href="#">CSCwh87343</a>	Cisco IOS XE Software Web UI Privilege Escalation Vulnerability

## Open Caveats – Cisco IOS XE Bengaluru 17.6.6

Identifier	Headline
<a href="#">CSCwh12668</a>	Standard loopback is not working when applied on both the ends on a back to back link.
<a href="#">CSCwa40025</a>	IMA3G card high temperature due to dynamic fan algorithm.

## Resolved Caveats – Cisco IOS XE Bengaluru 17.6.6

Identifier	Headline
<a href="#">CSCwd78618</a>	IMASER14A/S does not boot on ASR920.



Identifier	Headline
<a href="#">CSCwe38959</a>	The RS232 ASYNC pseudowire service with full scale seeing packet and byte drops intermittently.
<a href="#">CSCwf40953</a>	DS3_ADMIN_DOWN gets cleared after IM OIR.
<a href="#">CSCwf86864</a>	CEM traffic flow is dropped in one direction due to DEI bit set from router.
<a href="#">CSCwf49426</a>	PAIS alarm get reported after IM OIR.
<a href="#">CSCwe54549</a>	ASR-920 - SFP not detected due to checksum error.
<a href="#">CSCwe27336</a>	Error logs during reload in ASR920-24SZ-M variant.
<a href="#">CSCwh02460</a>	With x.21 configured observing underruns in cem counters.
<a href="#">CSCvy81362</a>	ASR920: Controllers are down due to LP-LOP alarm After CE reboots.
<a href="#">CSCwf07736</a>	CEM interface counters momentarily report error when x21 xconnect is cleared and re-established.
<a href="#">CSCwd46121</a>	Time stamp issue on Transparent clock for 1G PORTS.
<a href="#">CSCwd67723</a>	In IMA32D/IMA8D card, sometimes change in E1 controller config(after ctrlr flap)results in IM reboot.
<a href="#">CSCwf71463</a>	With traffic ON, when speed lowered on ASYNC port, SYNC port CEM traffic gets impacted.
<a href="#">CSCwe98227</a>	The <b>show version</b> does not display details of T1/E1 interfaces for 8D and 32D IMs.

## Open Caveats – Cisco IOS XE Bengaluru 17.6.5

Identifier	Headline
<a href="#">CSCwd90840</a>	Multicast data traffic is getting dropped over vpls
<a href="#">CSCwc77502</a>	Unexpected reload due to MLDPv6
<a href="#">CSCwd67723</a>	In IMA32D/IMA8D cards, any changes in the E1 interface configs (after interface flapping) results in IM crash and reboot
<a href="#">CSCwd16666</a>	The Bit Error Rate Testing (BERT) pattern does not sync while configuring network loop in 3GMS OC-3 ports

## Open Caveats – Cisco IOS XE Bengaluru 17.6.5 - Platform Independent

Identifier	Headline
<a href="#">CSCwc55520</a>	Traceback and IDB leak noticed when a RSP3 setup performs a switchover
<a href="#">CSCvy94083</a>	NCS4216:Running configuration syn to the NETCONF running data store taking more time .
<a href="#">CSCvy87800</a>	Remote Link Failure notification is disabled when configuring through YANG
<a href="#">CSCwb43369</a>	ASR920::Traceback seen when default made on all core intfs.

## Resolved Caveats – Cisco IOS XE Bengaluru 17.6.5

Identifier	Headline
<a href="#">CSCwc41135</a>	Continuous assertion and clear of LAIS on protect channel causing IPC failure
<a href="#">CSCwc80493</a>	APS - K2 byte not reflecting proper value during LRDI and LAIS conditions.
<a href="#">CSCwd04198</a>	A900-IMASER14A/S: when configurations are pasted in a specific order, line config is missing
<a href="#">CSCwc41115</a>	APS 1+1 Uni - Tx K2 to reflect Rx K1 channel number
<a href="#">CSCwc84627</a>	ASR-920-12SZ-IM - EOMER IM goes continuous reboot for a PCIE bus error
<a href="#">CSCwd48164</a>	EVPN statd resource leak after protocol flaps
<a href="#">CSCwc93296</a>	ASR-920-10SZ-PD /16.9.4/port Te0/0/10 went admin down after in successive reload
<a href="#">CSCvy09725</a>	Software solution to detect the BAD PSU
<a href="#">CSCwc79322</a>	Memory leak on ptpd_uea process
<a href="#">CSCwd26357</a>	rs485 with half-duplex configuration when reloaded, it gets into default full-duplex mode

## Resolved Caveats – Cisco IOS XE Bengaluru 17.6.5 - Platform Independent

Identifier	Headline
<a href="#">CSCwd66936</a>	UDP pseudowire stuck in Activating

Identifier	Headline
<a href="#">CSCwc21402</a>	Invalid BGP update when add-paths negotiated only for label (SAFI 4) and not unicast (SAFI1)
<a href="#">CSCwb91762</a>	RSP3: MSPW VC down points to Error Local access circuit is not ready for label advertise
<a href="#">CSCwb77093</a>	A BGP speaker may advertise a next-hop set to self when advertising an eBGP route to an iBGP peer.

## Open Caveats – Cisco IOS XE Bengaluru 17.6.4

Identifier	Headline
<a href="#">CSCwc60168</a>	Traffic drop in primary/active path when changes are made on backup path

## Open Caveats – Cisco IOS XE Bengaluru 17.6.4 - Platform Independent

Identifier	Headline
<a href="#">CSCwa30653</a>	MVPN Profile 14 : Data MDT traffic not flowing with 2 paths when OSPF cost configured on 1 path

## Resolved Caveats – Cisco IOS XE Bengaluru 17.6.4

Identifier	Headline
<a href="#">CSCwb32119</a>	IOT IMs fpd does not auto upgrade on RSP3
<a href="#">CSCwb01284</a>	ASR 900 Series PTP Sync degraded on Tester after primary PTP source failover to secondary

## Resolved Caveats – Cisco IOS XE Bengaluru 17.6.4 - Platform Independent

There are no resolved caveats in this release.

## Open Caveats – Cisco IOS XE Bengaluru 17.6.3

There are no open caveats for this release.

## Open Caveats – Cisco IOS XE Bengaluru 17.6.3 - Platform Independent

Identifier	Headline
<a href="#">CSCwb04551</a>	FRR not calculating backup route due to "primary_update_complete_pending:" flag set to 1
<a href="#">CSCwa30653</a>	MVPN Profile 14 : Data MDT traffic not flowing with 2 paths when OSPF cost configured on 1 path
<a href="#">CSCwa36608</a>	RSP3 ICCP stuck on CONNECTING state after RSP SO on Active PoA

## Resolved Caveats – Cisco IOS XE Bengaluru 17.6.3

Identifier	Headline
<a href="#">CSCvz42622</a>	TPOP T1 SATOP : Cable length range needs to be changed to be consistent with the IMA48D/IMA3G
<a href="#">CSCvy78284</a>	ASR920 will crash when zeroised RSA key is regenerated
<a href="#">CSCwa35351</a>	Raw-socket config-event use all the iomem when L1 is down
<a href="#">CSCwa59045</a>	Need to support few line level CLIs with "no" even without any cable attached.
<a href="#">CSCwa79398</a>	rs232 service on port8 gives SLIP errors when databits is set on other ports
<a href="#">CSCwa09302</a>	iMSG serial interfaces bitrate/sec data is displayed incorrectly in show command output
<a href="#">CSCvy92074</a>	MTU programming for mpls l2 vc may fail after interface flaps
<a href="#">CSCwa41638</a>	ASR920 MAC Table and L2VPN EVPN Table out of sync

## Resolved Caveats – Cisco IOS XE Bengaluru 17.6.3 - Platform Independent

Identifier	Headline
<a href="#">CSCwa37283</a>	RSP failover on NCS4200 showing several seconds of outage for L2VPN services

## Open Caveats – Cisco IOS XE Bengaluru 17.6.2

Caveat ID Number	Description
<a href="#">CSCvy78284</a>	Router crashes when zeroised RSA key is regenerated
<a href="#">CSCvz52848</a>	Raw-socket config-event use all the iomem if connected device L1 signals are down

## Resolved Caveats – Cisco IOS XE Bengaluru 17.6.2

Caveat ID Number	Description
<a href="#">CSCvy64788</a>	LLC frames get looped back due to autonomic networking
<a href="#">CSCvy91436</a>	Egress QoS classification issues are seen with Service instance 2 configuration on CE facing interfaces
<a href="#">CSCvz07477</a>	DWDM SFPs threshold value set to 0.0 dbm for RX/TX and -0.0 C for temperature.
<a href="#">CSCvz26979</a>	DHCP packets are not forwarded from client to server when DHCP snooping is enabled globally
<a href="#">CSCvz79672</a>	HQoS on egress TenGig interface does not work properly

## Resolved Caveats – Cisco IOS XE Bengaluru 17.6.2 - Platform Independent

Caveat ID Number	Description
<a href="#">CSCvz66346</a>	New Bridge-Domain are not added dynamically to POCH when TEFP-encap from-bd is configured
<a href="#">CSCvz25471</a>	NSO config push failure seen due to getconf on BD gives additional value mac learning

## Open Caveats – Cisco IOS XE Bengaluru 17.6.1

Caveat ID Number	Description
<a href="#">CSCvy92074</a>	MTU programming for MPLS Layer 2 VC may fail after interface flaps
<a href="#">CSCvz02352</a>	Error objects are seen in mlist area
<a href="#">CSCvy74356</a>	In T3 controller-CT3 E1 and CT3 mode the loopback local is not getting applied and the controller stays down

## Resolved Caveats – Cisco IOS XE Bengaluru 17.6.1

Caveat ID Number	Description
<a href="#">CSCvs50029</a>	Interface flaps and input errors seen with optics GLC-FE-100BX-D in ASR920-12CZ
<a href="#">CSCvu78738</a>	T3 counter names to be as per GR-820 standard names
<a href="#">CSCvv21542</a>	Command to change from dynamic to static FAN algorithm for Cisco ASR-920-24SZ-IM, Cisco ASR-920-24SZ-M, and Cisco ASR-920-24TZ-M
<a href="#">CSCvv42595</a>	REP flapping is seen randomly and frequently due to port down
<a href="#">CSCvv47918</a>	Block SATOP when controller is looped remotely (far end) for ACR/UPSR/CPG/STS1e
<a href="#">CSCvv55842</a>	DEI bit on C-TAG is not being preserved for Double tag to Double tag svc even if there is no rewrite
<a href="#">CSCvv74638</a>	RSP2-128: IMA1X frequent link down
<a href="#">CSCvv62123</a>	FPGA TX tables are not programmed for microbfd session after router reload in 17.4.1 release
<a href="#">CSCvv73275</a>	Applique type, syslog are misleading when a path configured with t3 is over-written with STSnC mode
<a href="#">CSCvv74342</a>	VPLSoBKPW: MAC is not flushed or withdrawn in remote peer on VC swichover from active to standby
<a href="#">CSCvv99456</a>	ACL entries with FRAGMENT keywords are not working on the router
<a href="#">CSCvw08879</a>	EVPN-IRB: Complete traffic drop seen in one direction after intf flap on spine or leaf with XE-XR interop
<a href="#">CSCvw32263</a>	ASR-920-24SZ-IM system is not going for shutdown when device booted without fan tray
<a href="#">CSCvw56612</a>	LOTR : <b>show lic</b> command does not show port details
<a href="#">CSCvw64784</a>	RSP2 CEM ACR: Not able to reuse same clock ID on another controller after you delete clock ID
<a href="#">CSCvw82333</a>	Continuous PCI role logging to trace file
<a href="#">CSCvx41010</a>	Failed to marshal xcvr_sync message: Bad address
<a href="#">CSCvr43362</a>	ASR-920-12SZ-IM, ASR-920-12SZ-A/ASR-920-12SZ-D: Fan speed control measures for overheating router

# Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at <http://www.cisco.com/web/applicat/cbsshelp/help.html>

