

IX5000 Release Notes for 9.1.4.1

September 28, 2022

Contents

What's new in this release	3
Open bugs.....	3
Resolved bugs	3
Bug Search Tool	3
Cisco TelePresence IX System Software Compatibility for Release 9.x	3

Intro –The IX Release 9.1.4.1 is a maintenance release, and this has been built on top of IX Release 9.1.4. The 9.1.4.1 COP file is signed with SHA512, please refer section "IX5000 9.1.4 COP file installation on CUCM" for installation and upgrade paths.

What’s new in this release

There are no features in this release. this release provides bug fixes only

Open bugs

Bug number	Severity	Affected product area	Description
CSCvh45762	3		IX5000 not accessible, got into hung state.

Resolved bugs

Bug number	Severity	Affected product area	Description
CSCwb24658	4	Touch 10 pairing and their API access for the Touch 10's.	IX5000 allows Weak Ciphers on ports 4051/4052

Bug Search Tool

We report open and resolved customer-found bugs of severity 1 to 3. You can find details about listed bugs and search for other bugs by using the Cisco Bug Search Tool. For more info on using the Bug Search, see [Bug Search Tool Help](#).

Cisco TelePresence IX System Software Compatibility for Release 9.x

The following table summarizes the IX software Release 9.x compatibility. The deployment of software shown in this matrix are tested and are supported by Cisco. Other combinations of products may work but are not supported and have not been tested.

Software version	IX 9.0.0	IX 9.0.1	IX 9.1.0	IX 9.1.1	IX 9.1.2	IX 9.1.3	IX 9.1.4	IX 9.1.4.1
Cisco Unified Communications Manager	10.5.2 (see note 3)	10.5.2 (see note 3)	10.5.2 (see note 3)	10.5.2 (see note 3)	10.5.2 (see note 3)	10.5.2 (see note 3)	10.5.2 (see note 3)	
	11.0.1 (see note 4)	11.0.1 (see note 4)	11.0.1 (see note 4)	11.0.1 (see note 4)	11.0.1 (see note 4)	11.0.1 (see note 4)	11.0.1 (see note 4)	12.5.1
	11.5.1 (see note 5)	11.5.1 (see note 5)	11.5.1 (see note 5)	11.5.1 (see note 5)	11.5.1 (see note 5)	11.5.1 (see note 5)	11.5.1 (see note 5)	14.0.1
	12.0.1 (see note 6)	12.0.1 (see note 6)	12.0.1 (see note 6)	12.0.1 (see note 6)	12.0.1 (see note 6)	12.0.1 (see note 6)	12.0.1 (see note 6)	

Software version	IX 9.0.0	IX 9.0.1	IX 9.1.0	IX 9.1.1	IX 9.1.2	IX 9.1.3	IX 9.1.4	IX 9.1.4.1
	note 6)	note 6) 12.5.1	note 6) 12.5.1	note 6) 12.5.1	note 6) 12.5.1	note 6) 12.5.1	note 6) 12.5.1 14.0.1	
Cisco TelePresence System (CTS) TX software (see note 1)	6.1.13	6.1.13	6.1.13	6.1.13	6.1.13	6.1.13	6.1.13	6.1.13
Cisco TelePresence System (CTS) software (see note 2)	1.9.12 1.10.16	1.9.12 1.10.16	1.9.12 1.10.16	1.9.12 1.10.16	1.9.12 1.10.16	1.9.12 1.10.16	1.9.12 1.10.16	1.9.12 1.10.16
Cisco TelePresence Collaboration Endpoint (CE8) Software	CE 9.4.0	CE 9.6.1	CE 9.7.1	CE 9.9.0	CE 9.12.3	CE 9.14.5	CE 9.15.3	CE 9.15.3
Cisco TelePresence Codec (TC7) Software	TC 7.3.12	TC 7.3.15	TC 7.3.17	TC 7.3.19	TC 7.3.21	TC 7.3.21	TC 7.3.21	TC 7.3.21
DX650/DX70/DX80	10.2.5(215)	10.2.5(215)	10.2.5(215)	10.2.5(215)	10.2.5(215)	10.2.5(215)	10.2.5(215)	10.2.5(215)
TelePresence Management Suite (TMS)	15.6	15.6 15.7 15.8 (see note 7)	15.6 15.7 15.8 (see note 7) 15.9	15.6 15.7 15.8 (see note 7) 15.9 15.10	15.10 15.11	15.13	15.13	15.13
TelePresence Manager Suite (TMS) with Phone Book support	15.6	15.6 15.7 15.8 (see note 7)	15.6 15.7 15.8 (see note 7) 15.9	15.6 15.7 15.8 (see note 7) 15.9 15.10	15.10 15.11	15.13	15.13	15.13

Software version	IX 9.0.0	IX 9.0.1	IX 9.1.0	IX 9.1.1	IX 9.1.2	IX 9.1.3	IX 9.1.4	IX 9.1.4.1
Cisco Meeting Server	2.3.2	2.3.2 2.5	2.6.1	2.6.3	2.6.3 2.9.1	3.1.0	3.3.0	3.5
Cisco TelePresence Conductor	XC 4.3.2 XC 4.3.3	XC 4.3.2 XC 4.3.3	XC 4.3.5	XC 4.3.6	XC 4.3.7	XC 4.3.7	XC 4.3.7	XC 4.3.7
Cisco TelePresence MCU	4.5(1.89)	4.5(1.98)	4.5(1.98)	4.5(1.98)	4.5(1.98)	4.5(1.98)	4.5(1.98)	4.5(1.98)
Cisco TelePresence Server (TS)	4.4(1.24)	4.4(1.28)	4.4(1.28)	4.4(1.29)	4.4(1.31)	4.4(1.31)	4.4(1.31)	4.4(1.31)
Cisco TelePresence Video Communications Server (VCS)	8.11	8.11 12.5	12.5	12.5	12.6	12.7	12.7	12.7
Cisco TelePresence Manager (CTS-Manager)	Not supported	Not supported	Not supported	Not supported	Not supported	Not supported	Not supported	Not supported
Cisco TelePresence Multipoint Switch (CTMS)	Not supported	Not supported	Not supported	Not supported	Not supported	Not supported	Not supported	Not supported

Note

- Supported on CTS500-32, TX1310-47, TX1310-65, TX9000, and TX9200.
- Supported on CTS500-37, CTS1000, CTS1100, CTS1300-65, CTS3000, CTS3010, CTS3200, and CTS3210.
- Minimum device package version to support disable "Proximity Content Share To Clients" for 10.5 is 10.5.(2.18155).
- Minimum device package version to support disable "Proximity Content Share To Clients" for 11.0 is 11.0.(1.25097).
- Minimum device package version to support disable "Proximity Content Share To Clients" for 11.5.1 is 11.5(1.16083).
- Minimum device package version to support disable "Proximity Content Share To Clients" for 12.0.1 is 12.0(1.22022).
- TMS 15.8 requires LSC to be installed on IX5000 (see [CSCvo06229](#)). To install LSC, see the *Administration Guide for Cisco TelePresence Software Release IX 8 and Later*, located here: <https://www.cisco.com/c/en/us/support/collaboration-endpoints/ix5000-series/products-maintenance-guides-list.html>.

See [Cisco TelePresence IX System Compatibility](#) for previous IX Software Releases.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)