



Cisco IP Phone 8800 Series Multiplatform Phones Release Notes for Firmware Release 12.0(2)

First Published: 2023-05-15

Last Modified: 2023-05-15

Release Notes

Use these release notes with the Cisco IP Phone 8800 Series Multiplatform Phones running SIP Firmware Release 12.0(2).

The following table describes the individual phone requirements.

Phone	Support Requirements
Cisco IP Phone 8800 Series Multiplatform Phones	BroadSoft BroadWorks 24.0 MetaSphere CFS version 9.5 Asterisk 16.0

Related Documentation

Use the following sections to obtain related information.

Cisco IP Phone 8800 Series Documentation

See the publications that are specific to your language, phone model, and multiplatform firmware release. Navigate from the following Uniform Resource Locator (URL):

<https://www.cisco.com/c/en/us/products/collaboration-endpoints/ip-phone-8800-series-multiplatform-firmware/index.html>

New and Changed Features

Configurable License Retry Timer for Authorization Failure

If an authorization operation to upgrade a license fails, the phone tries to authorize again after a time specified in seconds. If the delay is set to 0, the device does not do the retry.

Where to Find More Information

- *Cisco IP Desk Phone with Multiplatform Firmware (MPP) - Administration Guide*
- *XML Reference Guide for Cisco IP Phone Multiplatform Phones*

Controlling the TLS Minimum Value

You can control the phone minimum value of TLS with the new **TLS** parameter.

To enable this feature from the phone administration web page, use the **TLS Min Version** parameter under the **Security Settings** from **Voice > System**.

Where to Find More Information

- *Cisco IP Desk Phone with Multiplatform Firmware (MPP) - Administration Guide*
- *XML Reference Guide for Cisco IP Phone Multiplatform Phones*

Digest Algorithms for Hoteling Subscription

Phone now support SHA-256, SHA512, and SHA 256 digest algorithms for hoteling authentication. Prior to release 12.0(2), phone only has support for MD5 algorithm.

Where to Find More Information

- *Cisco IP Desk Phone with Multiplatform Firmware (MPP) - Administration Guide*
- *XML Reference Guide for Cisco IP Phone Multiplatform Phones*

Enabling Phone Authorization with RFC-8760

You can enable the phone authorization with RFC8760.

To enable this feature from the phone administration web page, use the **Auth Support RFC8760** parameter under the **SIP Settings** section from **Voice > Ext (n)**.

Where to Find More Information

- *Cisco IP Phone 8800 Series Multiplatform Phones Administration Guide*

Enabling the Webex Metrics Services

With Metrics Enable, enable the phone control of all metric services.

To enable this feature from the phone administration web page, use the **Metrics Enable** parameter under the **Webex** section **Voice > Phone**.

Where to Find More Information

- *Cisco IP Desk Phone with Multiplatform Firmware (MPP) - Administration Guide*
- *XML Reference Guide for Cisco IP Phone Multiplatform Phones*

Enabling PRT Upload at Crash Services

You can indicate whether to automatically upload the PRT package to the server when the phone crashes.

To enable this feature from the phone administration web page, use the **PRT Upload at Crash** parameter under the **Problem Reporting Tool** section **Voice > Provisioning**

Where to Find More Information

- *Cisco IP Desk Phone with Multiplatform Firmware (MPP) - Administration Guide*
- *XML Reference Guide for Cisco IP Phone Multiplatform Phones*

Enhancements in Hybrid Meetings Functionalities

Hybrid meeting functionalities have enhancements with the release 12.0(2). The following enhancements are implemented:

- Display of participants list and the participants status.
- Display of meeting recording status on the phone, such as recording and pause recording.
- Participants can mute or unmute themselves with softkey, hardkey, and headset. Also, mute and unmute status synchronizes with server side.
- Participants can mute or unmute video either with camera shutter or softkeys.
- Participants can join as a host or a guest and use PIN to join the hybrid meeting if the meeting is configured to be accessed only through a PIN.
- Shared line call retrieve while in a Webex meeting

Where to Find More Information

- *Cisco IP Phone 8800 Series Multiplatform Phones User Guide*
- *Cisco IP Desk Phone with Multiplatform Firmware (MPP) - Administration Guide*

Managing Participants List for Ad Hoc Conference

During an Ad Hoc conference, the host and the participants can show the participants list by pressing the **Participants** softkey on the phone. Also, both the host and the participants can add another person into the conference. However, only the host is allowed to remove a participant from the participant list.

Where to Find More Information

- *Cisco IP Phone 8800 Series Multiplatform Phones User Guide*
- *Cisco IP Desk Phone with Multiplatform Firmware (MPP) - Administration Guide*
- *XML Reference Guide for Cisco IP Phone Multiplatform Phones*

Synchronizing Mute or Unmute with Phone and Bluetooth Headset

Both the headset and the phone will sync their muted status. When the current call on the phone is active and the audio path is headset.

- The phone will be forced to mute if the headset is forced to be muted.
- The mute status of the headset will match that of the phone if it is not forced to be muted.

With the special requirement that the current call is active and the audio path is the headset, this function synchronizes the mute/unmute status between the phone and the headset.

The scope that supports this feature is listed in the following table:

Phone model	8845,8865,8851.8861
Phone version	12.0.2 and newer
Headset	Cisco 720 and 730 series
Headset version	All headset version do support mute or unmute sync, but only 1-12 version and newer will support force mute.



Note • This feature is not supported by non-Cisco headsets.

Where to Find More Information

- *Cisco IP Phone 8800 Series Multiplatform Phones User Guide*

Upgrade Firmware

You can upgrade the phone firmware with TFTP, HTTP, or HTTPS. After the upgrade completes, the phone reboots automatically.

Procedure

-
- Step 1** Click this link:
<https://software.cisco.com/download/home/286318380>
- On the **Software Download** web page that is displayed, ensure that **IP Phone 8800 Series with Multiplatform Firmware** is selected in the middle pane.
- Step 2** Select your phone model in the right pane.
- Step 3** On the next page that is displayed, select **Multiplatform Firmware**.
- Step 4** On the next page that is displayed, select **12.0.2** in the **All Releases > MPPv11** folder.
- Step 5** (Optional) Place your mouse pointer on the file name to see the file details and checksum values.
- Step 6** Download the corresponding file.
- 8845 and 8865: `cmterm-8845_65.12.0.2MPP0001.116_REL.zip`
 - Other phones in 8800 series: `cmterm-88xx.12.0.2MPP0001.116_REL.zip`
- Step 7** Click **Accept License Agreement**.
- Step 8** Unzip the file and place the files in the appropriate location on your upgrade server.
- The appropriate location is the TFTP, HTTP, or HTTPS download folder, depending on the protocol that you want to use for the upgrade.

Step 9 Upgrade the phone firmware with one of these methods.

- Upgrade the phone firmware from the phone administration web page:
 - a. On the phone administration web page, go to **Admin Login > Advanced, Voice > Provisioning > Firmware Upgrade**.

- b. In the **Upgrade Rule** field, enter the load file URL as described below.

Load file URL format:

```
<upgrade protocol>://<upgrade server ip address>[:<port>]/<path>/<file name>.loads
```

Examples:

- 8845 and 8865:

```
http://10.73.10.223/firmware/sip8845_65.12.0.2MPP0001.116.loads
```

```
https://server.domain.com/firmware/sip8845_65.12.0.2MPP0001.116.loads
```

- Other phones in 8800 series:

```
http://10.73.10.223/firmware/sip88xx.12.0.2MPP0001.116.loads
```

```
https://server.domain.com/firmware/sip88xx.12.0.2MPP0001.116.loads
```

- c. Click **Submit All Changes**.

- Upgrade the phone firmware directly from your web browser:

In the address bar of your web browser, enter the phone upgrade URL as described below.

Phone upgrade URL format:

```
<phone protocol>://<phone ip address[:port]>/admin/upgrade?<load file URL>
```

Load file URL format:

```
<upgrade protocol>://<upgrade server ip address>[:<port>]/<path>/<file name>.loads
```

Examples:

- 8845 and 8865:

```
https://10.74.10.225/admin/upgrade?http://10.73.10.223/firmware/sip8845_65.12.0.2MPP0001.116.loads
```

```
https://10.74.10.225/admin/upgrade?https://server.domain.com/firmware/sip8845_65.12.0.2MPP0001.116.loads
```

- Other phones in 8800 series:

```
https://10.74.10.225/admin/upgrade?http://10.73.10.223/firmware/sip88xx.12.0.2MPP0001.116.loads
```

```
https://10.74.10.225/admin/upgrade?https://server.domain.com/firmware/sip88xx.12.0.2MPP0001.116.loads
```

Note Specify the <file name>.loads file in the URL. The <file name>.zip file contains other files.

Limitations and Restrictions

Phone Behavior During Times of Network Congestion

Anything that degrades network performance can affect phone audio and, in some cases, can cause a call to drop. Sources of network degradation can include, but are not limited to, the following activities:

- Administrative tasks, such as an internal port scan or security scan.
- Attacks that occur on your network, such as a Denial of Service attack.

Caveats

View Caveats

You can search for caveats (bugs) with the Cisco Bug Search tool.

Known caveats are graded according to severity level, and are either open or resolved.

Before you begin

You have your Cisco.com user ID and password.

Procedure

- Step 1** Click one of the following links:
- To view all caveats that affect this release:
https://bst.cloudapps.cisco.com/bugsearch/search?kw=*%26amp;pdNm&is=1202&sb=al&bt=usV&pdNam=Cisco%20IP%20Phone%208800%20Series%20with%20Multiplatform%20Firmware
 - To view open caveats that affect this release:
https://bst.cloudapps.cisco.com/bugsearch/search?kw=*%26amp;pdNm&is=1202&sb=al&bt=usV&pdNam=Cisco%20IP%20Phone%208800%20Series%20with%20Multiplatform%20Firmware
 - To view resolved caveats that affect this release:
https://bst.cloudapps.cisco.com/bugsearch/search?kw=*%26amp;pdNm&is=1202&sb=f&bt=usV&pdNam=Cisco%20IP%20Phone%208800%20Series%20with%20Multiplatform%20Firmware
- Step 2** When prompted, log in with your Cisco.com user ID and password.
- Step 3** (Optional) For information about a specific caveat, enter the bug ID number (CSCxxxxxxx) in the **Search for** field, and press **Enter**.
-

Open Caveats

The following list contains the severity 1, 2, and 3 defects that are open for the Cisco IP Phone 8800 Series Multiplatform Phones that use Firmware Release 12.0(2).

For more information about an individual defect, you can access the online history for the defect by accessing the Bug Search tool and entering the Identifier (*CSCxxxxxxx*). You must be a registered Cisco.com user to access this defect information.

Because the defect status continually changes, the list reflects a snapshot of the defects that were resolved at the time this report was compiled. For an updated view of the resolved defects or to view specific bugs, access the Bug Search Toolkit as described in the [View Caveats, on page 6](#).

- CSCvy86354: MPP phones - 8845/8865 phones are randomly crashing.
- CSCwb27243: 8865 Crash - null pointer at libmmalvcp.so
- CSCwe55809: Personal contact calls play the distinctive ring while there's an active call on 8800 phones.
- CSCwf24915: 8865 no video since srtpm_srtpifUnprotect failure after hold resume several times
- CSCwf30157: Video phone: Camera led may be off in ad-hoc conference call

Resolved Caveats

The following list contains the severity 1, 2, and 3 defects that are resolved for the Cisco IP Phone 8800 Series Multiplatform Phones that use Firmware Release 12.0(1).

For more information about an individual defect, you can access the online history for the defect by accessing the Bug Search tool and entering the Identifier (*CSCxxxxxxx*). You must be a registered Cisco.com user to access this defect information.

Because the defect status continually changes, the list reflects a snapshot of the defects that were resolved at the time this report was compiled. For an updated view of the resolved defects or to view specific bugs, access the Bug Search Toolkit as described in the [View Caveats, on page 6](#).

- CSCwc61284: SSH is not available for phones running Multiplatform Phone (MPP) firmware.
- CSCwd01853: Cisco MPP Phones reboots when park and retrieve a call too fast.
- CSCwc29314: MPP phones (88xx/68xx/78xx) do not support dual registration with TCP.
- CSCwd62034: AWR-WB Media Type does not conform to RFC4867.
- CSCwd93487: 8851 KEM Memory leak causing reboot
- CSCvb65980: Nav hard key can't move cursor in Search Enterprise Directory.
- CSCwb85883: 88xx 88x5 the generated PRT toast content will overlap when a paging call is received.
- CSCwa95349: Cloud awareness: Phone will create new registration after reboot or for each refresh request
- CSCwd47209: The 'ACK' from MPP phone does not have 'Route' header.
- CSCwd56139: Cisco MPP phones "Debug" level log still print out when log level set to "Notice"
- CSCwd62809: Intermittent audio noises are heard on Webex calls
- CSCwe27819: Vulnerabilities in linux-kernel - multiple versions CVE-2016-0821

- CSCwe67157: Vulnerabilities in linux-kernel - multiple versions CVE-2023-26545
- CSCwe01828: Vulnerabilities in linux-kernel - multiple versions CVE-2021-4037
- CSCwe24803: Vulnerabilities in linux-kernel 4.9.118 CVE-2022-3643
- CSCwe38474: Held calls cannot resume on 8845/8865
- CSCwe46781: MPP 8865/8861 External Audio Output does not work after upgrade to 12.0.1
- CSCwc08931: Cisco MPP 8851 IP Phone with Cisco 561 USB headset are randomly crashing
- CSCwb65913: ICE: Phone becomes not operational when Media ports are not getting released
- CSCwd86078: Vulnerabilities in u-boot - multiple versions CVE-2022-34835 cmd_i2c.c
- CSCwe86166: 'Transfer' softkey in the Connected Key List is not working in 11.3.5 or later releases
- CSCwe46272: MPP 12.x not properly optimizing media via ICE on calls to LGW
- CSCwe46781: MPP 8865/8861 External Audio Output does not work after upgrade to 12.0.1
- CSCwf17564: MPP - 8851 Phone Lag/Freeze on 12.0.1 Firmware
- CSCwf23858: Selfview frozen for user in a 1:1 call

Cisco IP Phone Firmware Support Policy

For information on the support policy for phones, see the [Cisco IP Phone Firmware Support Policy](#).

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The following information is for FCC compliance of Class A devices: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio-frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case users will be required to correct the interference at their own expense.

The following information is for FCC compliance of Class B devices: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If the equipment causes interference to radio or television reception, which can be determined by turning the equipment off and on, users are encouraged to try to correct the interference by using one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Modifications to this product not authorized by Cisco could void the FCC approval and negate your authority to operate the product.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at www.cisco.com/go/offices.

The documentation set for this product strives to use bias-free language. For purposes of this documentation set, bias-free is defined as language that does not imply discrimination based on age, disability, gender, racial identity, ethnic identity, sexual orientation, socioeconomic status, and intersectionality. Exceptions may be present in the documentation due to language that is hardcoded in the user interfaces of the product software, language used based on standards documentation, or language that is used by a referenced third-party product.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2023 Cisco Systems, Inc. All rights reserved.