

Release Notes for Cisco RV110W up to Firmware Version 1.2.2.8

June 2020

Contents

This document includes the following topics:

- [Resolved Issues](#)
- [Related Information](#)

Resolved Issues

Issues Resolved in Release 1.2.2.8

Ref Number	Description
CSCvt28218	Cisco RV110W Router Command Injection Vulnerability
CSCvt28233	Cisco RV110W Routers Stack Overflow Vulnerability
CSCvt39797	Evaluation of rv110w for pppd buffer overflow vulnerability
CSCvs87870	Evaluation of rv110w for Kr00k attack - CVE-2019-15126

Issues Resolved in Release 1.2.2.5

Ref Number	Description
CSCvq31947	Evaluation of RV110W for TCP Sack vulnerabilities.

Release Notes

Issues Resolved in Release 1.2.2.4

Ref Number	Description
CSCvn18639	Cisco RV110W Routers Management Interface Buffer Overflow.

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Cisco Firmware Downloads	www.cisco.com/go/software Select a link to download firmware for Cisco Small Business Products. No login is required.
Product Documentation	
Cisco RV Series Routers	www.cisco.com/go/smallbizrouters

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2020 Cisco Systems, Inc. All rights reserved.

OL-31269-01