

Release Notes for the Cisco Small Business RV215W Series up to Firmware Version 1.3.1.7

June 2020

These Release Notes describe the updates and fixes in the Cisco Small Business RV215W firmware version 1.3.1.7. Overall security on the device has improved with this firmware release.

Contents

This document includes the following topics:

- [Resolved Issues](#)
- [Related Information](#)

Resolved Issues

Issues Resolved in Release 1.3.1.7

Number	Description
CSCvt28223	Cisco RV215W Router Command Injection Vulnerability
CSCvt28237	Cisco RV215W Routers Stack Overflow Vulnerability

Release Notes

Number	Description
CSCvt39801	Evaluation of rv2 15w for pppd buffer overflow vulnerability
CSCvs87874	Evaluation of rv2 15w for Kr00k attack - CVE-2019-15126

Issues Resolved in Release 1.3.1.5

Number	Description
CSCvq31952	Evaluation of RV215W for TCP SACK vulnerabilities.

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Cisco Firmware Downloads	www.cisco.com/go/software Select a link to download firmware for Cisco Small Business Products. No login is required.
Product Documentation	
Cisco RV Series Routers	www.cisco.com/go/smallbizrouters

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Copyright © 2020 Cisco Systems, Inc. All rights reserved.

OL-31270-01