

End-of-Sale and End-of-Life Announcement for the Access Point HWIC Supporting Japanese 5-GHz Radio Regulatory Requirements (with part number HWIC-AP-AG-J)

EOL5470—Amended

Cisco Systems[®] announces the end-of-sale and end-of life dates for the Access Point HWIC Supporting Japanese 5-GHz Radio Regulatory Requirements (with part number HWIC-AP-AG-J). The last day to order the Access Point HWIC Supporting Japanese 5-GHz Radio Regulatory Requirements (with part number HWIC-AP-AG-J) is January 12, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin.

Table 1 describes the end-of-life milestones, definitions, and dates for the Access Point HWIC Supporting Japanese 5-GHz Radio Regulatory Requirements (with part number HWIC-AP-AG-J). Table 2 lists the product part numbers affected by this announcement.

Table 1. End-of-Life Milestones and Dates for the Access Point HWIC Supporting Japanese 5-GHz Radio Regulatory Requirements (with part number HWIC-AP-AG-J).

Milestone	Definition	Date
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	January 12, 2007
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 12, 2007
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	July 8, 2008
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	July 8, 2008
End of Service Contract Renewal Date:	The last date to extend or renew a service contract for the product.	October 4, 2011
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	July 7, 2012

HW = Hardware, OS SW = Operating System Software, App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Product Description Number	Replacement Product Part Number	Replacement Product Description
---	---------------------------------	---------------------------------

HWIC-AP-AG-J	AP HWIC, 2 radios (2.4/5Ghz Radios for 802.11 a/b/g) Japan	HWIC-AP-AG-P	AP HWIC, 2 radios(2.4/5GHz radios for 802.11a/b/g) Japan
HWIC-AP-AG-J=	AP HWIC, 2 radios (2.4/5Ghz Radios for 802.11 a/b/g) Japan	HWIC-AP-AG-P=	AP HWIC, 2 radios(2.4/5GHz radios for 802.11a/b/g) Japan

Product Migration Options

Customers are encouraged to migrate to the access point HWIC with part number HWIC-AP-AG-P. Information about this product can be found at: http://www.cisco.com/en/US/products/ps6246/index.html.

Table 3. Product Comparisons

Feature Access Point HWIC Supporting Japanese 5 GHz Radio Regulatory Requirements (with part number HWIC-AP-AG-J)	Access Point HWIC Supporting 2.4- and 5 GHz Radios (with part number HWIC-AP AG-P)
---	--

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: http://www.cisco.com/go/tradein/. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:

http://www.cisco.com/en/US/ordering/or6/or17/order refurbished equipment program description. html

For More Information

For more information about the Access Point HWIC Supporting 2.4- and 5-GHz Radios (with part number HWIC-AP-AG-P), http://www.cisco.com/en/US/products/ps6246/index.html or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice



Americas Headquarters Capo Syatera, lec 170 West Bamer Odrebac Josés DA 85184-1760 USA sessolacoport DEL 258, 578-4700 Bibl 358-1701 (\$1851)

7ax 403 527-0683

Palar Paulific Handiquanismo Cauca Bysterria, Inc. 1806 Bysterrian Road 1806 O'C Capital Reser Singeriana 0008113 reseable accuraficies (SC 27772) Handido SC 177733 Campa Hassignarium: Capo Systems international SV Hassistongung 1978 1101 CH Assistanton The Welhassiston Straw guidepalescaped: Tex-4 14 200 (2007) Fáx-4 14 200 (2007) Fáx-4 10 10 20 70 7000

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

69307 Cisco Systems, inc. All rights reserved. COVR the Clace logo, and the Clace Square Bridge logo are tradements of Cisco Systems, inc. Changing the Way We Work, Like, Play, and Learn is a service mark of Cisco Systems, inc., and Accurse Register, Aistrest, EPA, Catalyst, CCDA, CODE, COE, COE, COE, COSP, Cisco the Cisco Striffed Intensistant Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems (logo Cisco Linky, Entraprise/Solver, Elher-Channel, Etherfest, Elher-Solver, Fellow Me Browsing, FormShare, GigaDrive, CigaStace, Home-Link, Insened Quotient, OS, Proces, BTTV, IQ Expertises that IQ logo, IO Not Readings Scorenzed, IQUIA Stuny, LightStreen, Linkye, MeetingPisco, MGK, Networking Academy, Network Registrat, Fox, ProCornect, StateMit, ScriptShare, SideCast, SMARThat, StackWise, The Festiont Way to increase Your Internet Quotient, and Transferth are registered trademarks of Cisco Systems, inc. and/or its efficients in the United States and contain other countries.

All other trademarks mentioned in this document or Websita are the property of their respective owners. The use of the word pertner does not imply a partnership relationship between Cisco and any other company, (0701%)

Printed in USA C51-388298-00 1/07