

End-of-Sale and End-of-Life Announcement for the Cisco Unity Connection Version 2.0

EOL6723

Cisco announces the end-of-sale and end-of life dates for the Cisco[®] Unity Connection Version 2.0. The last day to order the affected product(s) is May 2, 2009. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Customers are encouraged to leverage their Essential Software Service Contract (ESW) to upgrade to Cisco Unity Connection 2.1 or leverage their Unified Communications Software Subscription (UCSS) to upgrade to Cisco Unity Connection 7.0.

Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	April 2, 2009
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 2, 2009
Last Ship Date: App. SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 31, 2009
End of SW Maintenance Releases Date: App. SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	May 2, 2010
End of New Service Attachment Date: App. SW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 2, 2010
End of Service Contract Renewal Date: App. SW	The last date to extend or renew a service contract for the product.	July 29, 2011
Last Date of Support: App. SW		

 Table 1.
 End-of-Life Milestones and Dates for the Cisco Unity Connection Version 2.0

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product	Product Description	Replacement Product Part	Replacement Product
Part Number		Number	Description
SOFTWARE	Base Server Software		Cisco Unity Connection 2.1; Cisco Unity Connection 7.0

Product Migration Options

Customers are encouraged to migrate to the Cisco Unity Connection Version 2.1 or Cisco Unity Connection Version 7.0. Information about this product can be found at: http://www.cisco.com/en/US/products/ps6509/index.html.

Customers can leverage their Essential Software Service Contract (ESW) to upgrade to Cisco Unity Connection 2.1 or leverage their Unified Communications Software Subscription (UCSS) to upgrade to Cisco Unity Connection 7.0.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <u>http://www.cisco.com/go/tradein/</u>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the Cisco Unity Connection Version 2.0 through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <u>http://www.cisco.com/go/eos</u>.

Service prices for Cisco products are subject to change after the product End of Sale date.

For More Information

For more information about the Cisco Unity Connection Version 2.1 or Version 7.0, visit <u>http://www.cisco.com/en/US/products/ps6509/index.html</u>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: <u>http://www.cisco.com/en/US/products/prod_end_of_life.html</u>.

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

CCDE, CCENT, Cisco Eos, Cisco HealthPresence, the Cisco logo, Cisco Lumin, Cisco Nexus, Cisco StadiumVision, Cisco TelePresence, Cisco WebEx, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn and Cisco Store are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CoSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Dress, Cisco Systems, Cajoco Systems Capital, the Cisco Systems, Cisco Citte, CCNA, CCNP, CosP, CCVP, Cisco, the Cisco Systems, Cisco Citte, Cisco Meeting, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, Quick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0812R)

Printed in USA

C51-526787-00 04/09